

---

**To:** Nevada Division of Environmental Protection  
Nevada Environmental Response Trust

---

**Cc:** Nevada Environmental Response Trust Stakeholders

---

**From:** Jeff Lambeth, Director of Operations

---

**Date:** November 20, 2016

---

**Subject:** NERT – GWETS Operation Monthly Report – November 2016

---

At the request of the Nevada Environmental Response Trust (Trust), Envirogen Technologies, Inc. (ETI) is providing this summary of the groundwater extraction and treatment system (GWETS) operation and performance during November 2016.

### Summary of GWETS Operation

Envirogen Technologies, Inc. (ETI) mechanically operated the GWETS normally in November 2016. The average effluent flow rate was 935 gallons per minute (gpm) during November 2016. At the end of the month, the GW-11 Pond volume was at 40.8 million gallons (MG), which would allow 15.0 days of available additional storage in the event of an emergency plant shutdown with continued well field pumping. The water volume stored in the GW-11 Pond increased approximately 2.8 MG from the end of October 2016. Figure 1 in this report depicts the actual and projected GW-11 pond volumes and additional storage available.

The influent perchlorate concentration to the FBR plant averaged 85 mg/L for the month, with a maximum concentration of 95 mg/L. In comparison, the influent perchlorate concentration for the month of October 2016 averaged 86 mg/l, with a maximum concentration of 110 mg/l.

Analytical data indicate that the permitted effluent discharges at GWETS Outfall 001 were within the NPDES permitted numerical discharge limits (Please see Attachment A, prepared by Ramboll Environ).

### Enhanced Operational Metrics

Tables 1 and 2 provide a summary of the current GWETS operational metrics data for flow rates, perchlorate and chromium concentrations, and mass removal. Figure 2 graphically presents historical perchlorate and chromium mass flux information.

### Operational Issues

All routine plant repairs conducted by ETI were performed in accordance with the NERT Perchlorate Treatment System Operations Manual. The following is a list of operational issues and major repairs and/or equipment replaced during this reporting period.

## 1. GW-11

- Continued maintenance activities at the Lift Stations required the operators to use the GW-11 pond for influent equalization beginning 11-2-16. High winds and excessive algae forced the operators to switch back to using the TK-101 tanks for influent equalization beginning 11-27-16. The plant operators adjusted operations to compensate for the change in influent equalization.

## 2. Biological Plant

There were no significant plant interruptions. There were five unplanned diversions into GW-11 for the month of November. Below is a description of the short duration events that occurred:

- Effluent Diversion to GW-11 on November 1<sup>st</sup> at 7:45 am to 11:00am. The plant effluent was diverted for precautionary measures. Changes in flow characteristics from LS2 due to the newly installed VFD's caused an unexpected change in plant load. Adjustments were made to LS2 flow and the effluent was returned to the wash after in-house lab results confirmed compliance. A total of 169,617 gallons were diverted.
- Effluent Diversion to GW-11 on November 2<sup>nd</sup> at 2:00pm to 2:54pm. The plant effluent was diverted for precautionary measures. Maintenance activities on the GWTP required a change in the TK-101 influent equalization flow path to GW-11. This change in flow path created a sudden change in the plant load. Adjustments were made to plant operations and the effluent was returned to the wash after in-house lab results confirmed compliance. A total of 46,799 gallons were diverted.
- Effluent Diversion to GW-11 on November 15<sup>th</sup> at 10:15am to 1:10pm. The plant effluent was diverted due to maintenance activities on the effluent pipe line at LS1 as part of the upgrade project at that location. The effluent was returned to the wash upon completion of those specific activities. A total of 112,099 gallons were diverted.
- Influent Diversion to GW-11 on November 18<sup>th</sup> at 1:45pm to 3:15pm. The plant influent was diverted due to maintenance activities on the effluent diversion valve on the effluent pipe line at the EQ area. The plant influent was all directed to the GW-11 pond and the FBR's were put in recycle during the maintenance activities. No water was treated during the short duration of these activities.
- Effluent Diversion to GW-11 on November 18<sup>th</sup> at 4:30pm to 5:13pm. The plant effluent was diverted due to maintenance activities on the effluent pipeline air release valves (Combo valves). The effluent was returned to the wash upon completion of those activities. A total of 40,656 gallons were diverted.

## 3. Spills

There were two reportable spills in the month of November.

At 3:45 PM PDT on November 2, 2016, the influent tank overflowed due to a failing level sensor. This event was summarized in the Trust's letter to NDEP BWPC dated November 7, 2016 submitted consistent with permit requirements.

- On Friday November 18, 2016 the Trust received a call from Tetra Tech that there appeared to be an air and vacuum release valve (combo valve) leaking along the effluent pipeline. The Trust immediately contacted Envirogen at 4:24 pm and informed Envirogen that a problem had been reported along the pipeline. After inspection the Trust determined that 5 gallons of treated effluent had spilled from the valve access enclosure to the adjacent soil. This event was summarized in the Trust's letter to NDEP BWPC dated December 1, 2016 submitted consistent with permit requirements.

#### 4. Maintenance

- Major maintenance performed by ETI in the month included:
  - I. GWTP AC-1 - Air Compressor- The electrical contactor switch failed. ETI replaced the switch with a new contactor and returned the air compressor back to normal operation.
  - II. MCC-4, EQ Area- ETI experienced a communication loss between the EQ Area and Control Room. The electrical grounding and wire connections were replaced and the system was returned to normal service.
  - III. GWTP MCC-4, EQ Area –The PLC Power Supply failed. ETI replaced the Power Supply and Profibus Card and the system was returned to normal service.
  - IV. GWTP P-7, Clarifier sludge recirculation pump – The pipe was clogged on the suction side of the pump. The clarifier was taken offline and drained to inspect the clogged line. The debris in the bottom of the vessel was removed and the system was put back into service.
  - V. ART-1, AWF extraction well - The well pump motor failed due to age and normal wear and tear. The system was removed, the pigtail and motor were replaced with the same size motor – 1 hp Franklin motor. The well was returned to normal service.
  - VI. D-501 – The DAF skimmer system required adjustment to the flight tension. Once the DAF vessel was drained and cleaned, the chain system was adjusted and several links, rollers, pins and shafts were replaced. The system was put back online with no further issues.
  - VII. P-501 – The DAF pressurization pump was removed due to repair the gearbox seals and a worn mechanical seal. The pump was sent to Motion Industries where the work was performed and the pump was put back into normal service.
  - VIII. T-501 – A new DAF pressurization tank was put into place to replace the rusted tank that showed signs of interior failure in the walls of the tank.
  - IX. I-Q, IWF extraction well - The well pump motor failed due to age and normal wear and tear. A new ½ hp Franklin motor was installed (the same model and size as previous), as well as, all new wiring. The well was returned to normal service.
  - X. I-AB, IWF extraction well - The originally installed discharge piping inside the well casing failed. The original piping was 1” threaded SCH 40 PVC. The pipe was replaced with 1” Boreline hose to match all the other IWF wells. There was no spill into the environment related to this repair. The pump was placed back into the well and is ready for service.

- XI. P-102A, FBR Influent Pump - After discovering a leaking mechanical seal, the pump and motor were removed and sent to Motion Industries warranty work. This seal had been replaced three months prior. The repairs were expedited and the pump and motor were placed back into normal service.
  - XII. The Lift Station High High level switch at LS#2 – This switch was producing a false signal causing intermittent shutdowns of LS#3. The cause of the false signals was diagnosed as a corroded terminal block. The wiring was repaired stopping the false signal and the lift station was returned to normal operating service.
  - XIII. Combo Valves – One of the combo valves on the effluent pipeline had a small amount of debris in the rolling seal causing it not to seal completely. This allowed for a small amount of water to pass through. All water was contained within the valve box. Different rolling seals and floats were installed to better compensate for the low pressure in the line. The interval for inspecting the combo valves has also increased to monthly instead of quarterly.
- Preventative Maintenance completed or being performed by ETI in the month included:
    - I. Sequence Test-Test all Alarm. Tested all signals related to the automatic plant shutdown sequencing. No alarm or sequencing issues were noted.
    - II. ETI Calibrated and Standardized all FBR pH and ORP online analyzers.
    - III. LT-551, DAF. ETI Cleaned and calibrated level transmitter probe, cleaned sight glasses, checked gauges, and checked overall condition.
    - IV. All safety PM's were completed including ladders, slings, safety harnesses and extension cords.
    - V. Quarterly DAF vessel inspections were completed to ensure there are no faults or defects in the vessel itself. Both vessels were drained, pressure washed, and inspected. No faults were identified and the system was returned to normal service.
    - VI. The solids were removed from the degassifier tank at the GWTP.
    - VII. The Effluent Sand Filter was inspected for faults. The only fault identified was an airlift pump that had a bad glue joint that separated the air chamber from the lift. The joint was repaired and placed back into normal service.

## GWETS Upgrades and Facility Projects

The following is a summary of the initiatives in-progress during the reporting period at the direction of the Trust:

### 1. AP-5 Solids Removal

Tetra Tech continued to move forward with the construction of the three large tanks associated with the AP-5 Solids Removal project.

### 2. Lift Station #1 upgrades

ETI continued the process of implementing infrastructure improvements at Lift Station 1 and the addition of an Ion Exchange system was approved by NERT. During the reporting period, ETI completed most of the site preparations and equipment has begun to be delivered. Currently the project is scheduled to be complete by December 31, 2016.

### 3. IWF well modifications

A proposal for the IWF is being prepared to address the Trust's desire to improve the flow meter accuracy and installation of VFDs on the extraction pumps. This proposal was submitted by ETI Engineering and is currently under review by the Trust.

#### **4. Spill containment enhancements**

A proposal for secondary containment modifications has been assembled by ETI Engineering and is currently under review by the Trust.

### **ECT Audit Findings**

ETI has been addressing the recommendations provided in the Independent Audit of the GWETS performed by ECT. Table 3 summarizes the status of the ECT Audit findings. Progress is reported in the Status column. Updates from the prior reporting period appear in bold, underlined text.

### **Equipment Availability Tracking**

ETI operators continue to update the equipment tracking form on a weekly basis at a minimum, or whenever there is a change in the status of key equipment. During regular site visits, Tetra Tech field personnel verify the entries on the form, including both the operating status and confirmation of the inventory of required shelf spares. The equipment tracking form is included as Attachment B.

### **GWETS Staffing**

ETI continues with 24-hour staffing of the GWETS at the direction of the Trust and continues to follow the security procedures in the Standard Operating Procedures (SOP).

# Tables

---

*Operational Metrics*

Nevada Environmental Response Trust   Groundwater Extraction and Treatment System   Monthly Stakeholder Metrics				
Location ID	Average Flow Rate (gpm)	Perchlorate (mg/L) <sup>4 5</sup>	Chromium (TR) (mg/L) <sup>4 5</sup>	Chromium(VI) (mg/L) <sup>4 5</sup>
SWF Total Extraction <sup>2</sup>	549 <sup>1</sup>	10	ND	0.00030
AWF Total Extraction <sup>2</sup>	377 <sup>1</sup>	114	0.30	0.32
IWF Total Extraction <sup>2</sup>	59 <sup>1</sup>	765	8.0	8.3
IRM Total Extraction	1.0	2,173	NA	0.033
GWTP Effluent <sup>3</sup>	65	832	0.29	ND
GW-11 Influent <sup>2</sup>	797	97	0.11	0.067
GW-11 Effluent/ FBR Influent <sup>3</sup>	935	85	0.059	0.032

## Notes:

TR = Total Recoverable; NA = Not Analyzed; ND = Not detectable above laboratory method detection limit (Chromium (VI) = 0.25 ug/L).

1: Sum of daily average flow for individual wells.

2: Perchlorate and chromium TR sampled monthly, values reported from TestAmerica.

3: Perchlorate, chromium TR and chromium (VI) sampled weekly, values reported from TestAmerica.

4: All concentrations reported are monthly flow weighted averages.

5: ND analytical values are treated as zero values in the flow weighted average calculations.

Nevada Environmental Response Trust   Groundwater Extraction and Treatment System   Monthly Stakeholder Metrics			
Location ID	Perchlorate (lbs/month) <sup>1</sup>	Chromium (TR) (lbs/month) <sup>1</sup>	Chromium (VI) (lbs/month) <sup>1</sup>
SWF Total Extraction	2,008	0.00	0.06
AWF Total Extraction	15,583	41	44
IWF Total Extraction	16,233	170	177
IRM Total Extraction	1,141	NA	0.02
GWTP Effluent	19,671	6.9	0.00
GW-11 Influent	27,895	32	19
GW-11 Effluent/FBR Influent	28,675	20	11

## Notes:

TR = Total Recoverable; NA = Not Analyzed.

1: Total lbs extracted is calculated from flow weighted average concentration and average flow (see Table 1).



**Table 3 - Status of ECT Audit Recommendations**

<b>LS #1 and Seep Field</b>			
<b>Number</b>	<b>Ranking</b>	<b>Issue Description</b>	<b>Status</b>
1	Priority A	<p>Lift Station #1 should be evaluated for repair and upgrade.</p> <p>a. A high priority should be placed on abandoning and replacement of the flexible hoses and the aging parallel piping at Lift Station #1.</p> <p>b. Lift Station #1 should be re-evaluated to assure that the designs, and the materials of construction, are consistent with the current and future facility needs in full recognition that this operation is likely to continue for a significant period of time.</p>	<p><u>In Process</u></p> <p>a. As part of the LS1/IX Upgrade, these hoses will be replaced with hard pipe manifold system. The upgrade is currently in progress and this should be completed in 12/31/16.</p> <p>b. The materials of construction have been evaluated and items that need upgrade will be replaced following the LS1/IX upgrade. The upgrade is currently in progress and this should be completed in 12/31/16.</p>
2	Priority A	<p>The SWF vaults should be sealed using commercially available sealants used in Industry and wastewater treatment to prevent exfiltration.</p>	<p><u>Completed.</u> ETI inspected all Seep Well Field vaults and sealed all vault penetrations with recommended foam.</p>
3	Priority A	<p>The SWF well fields should be inspected and aging wells replaced as practicable. Much of the above grade plumbing is old and unreliable. Also, some of the wells cycle on and off fairly rapidly. This would indicate that the groundwater has been lowered or more likely, the well screens have become fouled, limiting the flow into the well.</p> <p>The local hydrogeology around the rapidly dewatering wells should be analyzed and the wells should be replaced if it is determined that they have become fouled.</p>	<p><u>In Process</u></p> <p>Removal of above grade piping at LS-1 will be completed as part of the IX Treatment System installation to be completed by 12/31/16. Aquifer evaluation of the SWF is currently ongoing as part of the COP. If necessary, well maintenance activities will be performed to improve well yield.</p>
4	Priority A	<p>The Audit Team recommends that ETI consider using a screening process capable of managing a higher solids content to address issues including the Boatmen bug spawns.</p>	<p><u>Closed -</u> This issue occurs twice per year in spring and fall for a few weeks each time. ETI feels this is not necessary in light of future plans for the GW-11 pond, and this issue would be mitigated by those plans. Based on ETI's research, this is a common problem in ponds in the area.</p>
5	Priority A	<p>The auditors observed an area where crystals of unknown nature have formed at PC-99 R2/R3. NERT should sample the observed crystals and analyze their composition at the earliest opportunity. The R3 well enclosure had standing water and crystals formed both inside and outside of the well vault. The Audit Team also noted a damp area extending from the R3 vault to about 10 to 15 feet from the enclosure. The Audit Team did not collect samples from the damp area or of the observed crystals. While it is possible that the observed crystals are not perchlorate but rather salts resulting from the extremely hard water in the area, with no data available, caution should be observed.</p>	<p><u>In Process</u></p> <p>Crystals were hard water calcium from a leaking flange gasket. This area was cleaned and a new gasket was installed.</p> <p><b><u>NERT collected a soil sample immediately below the salt crystals previously observed on November 18, 2016 for laboratory analysis. During the sampling event NERT discovered that the salt crystals were no</u></b></p>

			<b><u>longer present on the side of the well vault. Salt crystals in this area tend to be transient in nature. The analytical results indicate the presence of perchlorate in soil at a concentration of 19 mg/kg. This concentration is below the NDEP's Residential Basic Comparison Level. However, this situation will be further evaluated as part of the Phase 2 Remedial Investigation.</u></b>
6	Priority B	A detailed inspection of the SWF underground piping should be performed to estimate the remaining useful life.	<u>In Process</u> Removal of above grade piping at LS-1 will be completed immediately following the IX Treatment System installation to be completed by 12/31/16. As part of the RI/FS NERT will re-evaluate the SWF and its conveyance piping.
7	Priority B	All abandoned equipment should be removed from the operating areas of the operation.  To be further examined by the Trust.	<u>Ongoing</u> Abandoned equipment will be removed as various upgrades occur throughout the plant.
8	Priority B	The access doors at the SWF vaults should be replaced with doors that have modern safety latches and are physically manageable in order to make inspection access easier for the operating staff.	<u>Closed</u> ETI does not believe that modifications are necessary to operate the doors. Our staff believe they can safely operate the doors.
9	Priority B	Concurrent with plans to expand the loading of perchlorate to the FBRs, the capacity of the solids handling systems in general, and the DAFs specifically, should be evaluated for upgrade.	<u>Closed</u> Completed, both of the DAFs have recently been rehabilitated. The DAF design is more than adequate for the solids generated a full plant load.
10	Priority B	The remaining Penn Valley Double Disc Pumps should be replaced with air-driven double diaphragm pumps as they fail. There should be a review of the need for additional process air to operate the new pumps.	<u>In Process</u> Currently ETI is in progress with the pump replacements. Two of the 4 pumps have been replaced with air-driven diaphragm pumps, the remaining 2 Penn Valley Double Disc Pumps will be replaced as they fail.
11	Priority C	A hydraulic analysis should be performed from the discharge port of the variable frequency pumps to the discharge point at the Las Vegas Wash to identify (and eliminate) the areas of highest flow loss.	<u>Complete</u> NERT has completed a pipeline flow evaluation and is planning infrastructure upgrades in 2017 to address this issue.
12	Priority C	As the submersible pumps reach the end of their useful life, they should be replaced with more appropriate technology, such as vertical turbine pumps, for increased reliability and ease of service.	<u>Complete</u> Vertical turbine pumps were installed as part of the upgrade project for both LS-3 and LS-2.

<b>Job Cal (Maintenance Management Program) and Data Control</b>			
<b>Number</b>	<b>Ranking</b>	<b>Issue Description</b>	<b>Status</b>
1	Priority A	Incorporate all contractor supplied maintenance into the JobCal system.	<u>Complete</u> All contractor supplied maintenance activities are being logged in the JobCal computer maintenance management system.
2	Priority B	Improve detail captured in JobCal to include actual level of effort expended in repairs.	<u>Complete</u> ETI has worked with the staff to improve the capture of information and detail that is logged into the JobCal computer maintenance management system.
3	Priority B	Streamline the management of water quality data to assure accountability.	<u>Complete</u> NERT has established a new data transfer protocol that streamlines the management of water quality data amongst the NERT team members. External accessibility will be improved with the implementation of GWETS/NET
<b>Operations Monitoring</b>			
<b>Number</b>	<b>Ranking</b>	<b>Issue Description</b>	<b>Status</b>
1		Complete conversion of All SCADA systems to a single system – presumably the Siemens system.	<u>In Process</u> The existing Chromium Treatment Plant control system will be replaced when this plant is upgraded or replaced.
2		Incorporate online access and back-up to allow ETI experts to remotely observe and control operations.	<u>In Process</u> GWETS/NET will provide remote access to operational data by NERT and ETI.
<b>Facilities Maintenance</b>			
<b>Number</b>	<b>Ranking</b>	<b>Issue Description</b>	<b>Status</b>
1	Priority A	Infrared electrical surveys should continue to document any potential degradation of electrical and mechanical connections over time and use.	<u>Complete</u> The initial plant survey was completed and actions where needed was taken. The next survey has been incorporated into Job Cal as a re-occurring (PM) event, and is scheduled again for December 2016.
2	Priority A	The electrical grounding within the plant should also be reassessed to make sure that no ground faults are present.	<u>Complete</u> ETI brought in a certified electrician who identified motor skids that were not properly grounded. Since then ETI has installed grounding where it was missing. Based on the site electrical drawings, all known discrepancies have been addressed.
3	Priority A	Limit the length of wiring run from the VFD to the motor/pump units to a maximum of 150 feet.	<u>Complete</u> Any VFD systems to be installed will have a limited cable run, less than 150 feet or based on manufacturers

			<i>recommendations.</i>
4	Priority A	The motor bearings in motor units operated with VFDs should be lubricated utilizing conductive grease to prevent electrical arcing within the motor bearings even if a ground fault occurs.	<u>Complete</u> <i>ETI is currently using conductive grease. The use of conductive grease is currently being logged into Job Cal.</i>
5	Priority A	Utilize full Asset Management Capabilities of Job Cal. As per above,	<u>Complete</u> <i>ETI has further leveraged Job Cal and will continue to expand its use in facility operations.</i>
6	Priority A	Incorporate age of equipment and expected serviceable life for all major equipment.	<u>Complete</u> <i>ETI has further leveraged Job Cal and will continue to expand its use in facility operations.</i>
7	Priority A	Incorporate all contractor supplied maintenance into the JobCal system.	<u>Complete</u> <i>ETI has further leveraged Job Cal and will continue to expand its use in facility operations.</i>
8	Priority B	Improve detail captured in JobCal to include actual level of effort expended in repairs.	<u>Complete</u> <i>ETI has further leveraged Job Cal and will continue to expand its use in facility operations.</i>
<b>Training</b>			
<b>Number</b>	<b>Ranking</b>	<b>Issue Description</b>	<b>Status</b>
1	Priority B	Improved documentation of operator training is recommended. The operators have been taught how to operate the equipment but the documentation and supporting information for training provided and received was lacking – unlike the other training provided on-site.	<u>In Progress</u> <i>ETI is continuing to improve new employee training and documentation of said program. The training program and the appropriate documentation will be complete by April 2017.</i>
<b>HazWaste and Recycling</b>			
<b>Number</b>	<b>Ranking</b>	<b>Issue Description</b>	<b>Status</b>
1	Priority B	Install a can puncturer and develop a program to handle aerosol cans to assure that the waste cans are "RCRA empty" at atmospheric pressure.	<u>Complete</u> <i>Complete and on-site.</i>
2	Priority B	Containers storing used oil should be labeled correctly and be moved to a location where they are protected from the elements.	<u>Complete</u>
3	Priority C	As a good management practice for CESQGs obtain an EPA identification number.	<u>Completed by NERT.</u>
4	Priority C	As a good management practice for CESQGs develop and maintain a waste manifest tracking log to manage all of the shipping and receiving manifests for all waste shipments.	<u>Completed by NERT</u>
5		Continue to manage universal waste per the universal waste requirements.	<u>Complete and Ongoing</u>
6	Priority C	Develop a more concise chemical inventory with annual capacities and usages for all applicable chemicals.	<u>In Progress</u> <i>All chemicals are inventoried each month. Usage of each chemical is logged into the HACH Wims Data Management</i>

			<u>software.</u>
7	Priority C	An applicability study should be completed to determine if the facility is subject to TRI Form R reporting.	<u>Closed</u> After review, ETI does not see the need for this study and is in complete compliance with all reporting currently required.

Notes:

Changes in activity status from the prior month are displayed in the Status column with **bold, underlined font.**

# Figures

---

*Operational Metrics*





Figure 2 - Historical Perchlorate Mass Flux





# Attachment A

---

*NPDES Tracking Sheet (Prepared by ENVIRON)*

Summary table with columns for Continuous (Flow Rate, Daily Maximum (WGD)), Daily samples, composited weekly (Perchlorate), Weekly samples (pH, Hexavalent Chromium, Total Chromium, Total Suspended Solids (TSS), Total Iron, Total Ammonia as N, Total Phosphorus as P), Weekly samples, collected separately (BOD5 (inhibited)), and Quarterly sample (Manganese).

Main data table with columns: Daily Grab Sample Dates, Composite Sample Date, ug/L, lbs/day, Sample Date, S.U., mg/L, mg/L, mg/L, lbs/day, mg/L, lbs/day, mg/L, lbs/day, mg/L, lbs/day, mg/L, lbs/day, Sample Date, mg/L, lbs/day, mg/L, lbs/day.

Note: All analytical responsibilities are performed by TestAmerica Laboratories, Inc. (TestAmerica) in Irvine, California, unless otherwise indicated.  
\* = The 39 ug/L result is believed to be from cross-contamination during compositing of the sample. Following receipt of the 39 ug/L sample result, the 7 individual daily effluent samples collected between 7/31 and 8/6, as well as a new 7-day composite sample were submitted for perchlorate analysis. All re-analyzed effluent samples were non-detect for perchlorate.

NA = Not Available To Date  
ND = Not Detected above laboratory reporting limit; concentration in adjacent cell to right is one-half the reporting limit (per Permit condition)  
-- = Analyte detected; see column adjacent to right  
Last Updated: December 2, 2016

# Attachment B

---

*Equipment Tracking Form*

Sub-System	P&ID	Description	Status <sup>1</sup>	Checked	Criticality <sup>2</sup>	Notes
<b>Main Plant Equipment</b>						
<b>1 Seep Wells and Lift Station 1</b>						
1.01		<i>Seep Well Field, 9 wells</i>	Running			A new saddle was installed to tie in the piping from PC-99r2 into the casing of PC-99r3.
1.02		<i>Lift Station 1 Lift Pump A</i>	Running			
1.03		<i>Lift Station 1 Lift Pump B</i>	Standby			
1.04		<i>Area in and around Lift Station 1</i>	Running			The upgrades around the lift station have begun to include new lighting, controls, piping for the IX unit, containment and removal of old piping and controls.
<b>2 Athens Road Wells and Lift Station 3</b>						
2.01		<i>Athens Road Well Field, 9 wells</i>	Running			
2.02		<i>Lift Station 3 Lift Pump A</i>	Standby			
2.03		<i>Lift Station 3 Lift Pump B</i>	Running			The 6" steel swing check valve was removed and serviced for proper operation by Raphael Const.
2.04		<i>Area in and around Lift Station 3</i>	Running			
<b>3 Lift Station 2 and Transmission Pipelines</b>						
3.01		<i>Influent Pipeline</i>	In operation			
3.02		<i>Effluent Pipeline</i>	Running		1	The combo valve inspection frequency has changed to monthly as a result of the faulty combo valve found on 11-18. New seats and floats were installed to adjust for the low pressure on the line at that point.
3.03		<i>Lift Station 2 Lift Pump A</i>	Running			
3.04		<i>Lift Station 2 Lift Pump B</i>	Standby			
3.05		<i>Area in and around Lift Station 2</i>	Running		2	LSHH float switch had a poor communication connection causing a false signal to show up. The terminal block it was attached to was bypassed and the wires were connected directly inside of the junction box. The false signal has since stopped. There is no risk bypassing the terminal block.
<b>4 Interceptor Wells and Cr Treatment Plant</b>						
4.01		<i>IWF Well Field, 30 wells</i>	Running		3	The piping on I-AB was broken off due to the faulty installation by the original contractors. This is not a well that pumps daily. The 1"PVC SCH 40 piping was removed and replaced with 1" Boreline hose. A new 1/2 hp Franklin motor was installed on I-Q. This was an old motor that was worn. (Same size and model of motor as on the rest of the well field.)
4.02		<i>Ferrous Sulfate Feed System</i>	Running			
4.03		<i>Polymer Feed System</i>	Running			

Status Codes

Running - Unit is in operation  
 Standby - Spare or duplicate, not currently in operation  
 Maintenance - Out of service for maintenance  
 Off - Not currently needed for use, but can be placed in service

Criticality Codes

1 = Critical - Cannot continue with operation until repairs made  
 2 = Important - Can still operate safely and in compliance with permits, but risks are increased  
 3 = Moderate - Work needs to be performed, but plant can still operate with redundancy that is in place  
 4 = Low - Minor repairs that in no way alter the performance of the plant

Sub-System	P&ID	Description	Status <sup>1</sup>	Checked	Criticality <sup>2</sup>	Notes
4.04		Clarifier	In operation		1	The clarifier was taken offline to remove debris from the base of the tank that is used for transferring sludge to the conditioning tank. The settling tubes were also removed and inspected. A new 3" Spears butterfly valve was installed at the base of the vessel in place of the work 3" steel wafer valve. Solids were also removed from the degassifier tank and transferred into totes which was later processed through GWTP.
4.05		Filter Press	Running			
4.06		GWTP Effluent Tank	In operation			
4.07		Interceptor Booster Pump A	Running			
4.08		Interceptor Booster Pump B	Standby			
4.09		Area In And Around GWTP	Running		3	The contactor for the air compressor switch failed. A new part was ordered and installed. During the down time the back up compressor was put online and supplied the plant with the necessary air to operate.
<b>5</b>		<b>Equalization Area and GW-11 Pond</b>				
5.01	PID10A	Pond GW-11	In operation			
5.02	PID10A	Pond Water Pump - P101A	Running		2	The pump was re-installed with new motor bearings and mechanical seal after a leak was found at the seal. Faulty motor bearings were the cause of the seal failure. The pump is back in operation.
5.03	PID10A	Pond Water Pump - P101B	Standby			
5.04	PID10A	Equalization Tanks	In operation			
5.05	PID10A	Area in and Around EQ	In operation			
5.06	PID10A	Raw Water Feed Pump - P102A	Standby			
5.07	PID10A	Raw Water Feed Pump - P102B	Running			
5.08	PID10A	F-101 Filters	Running		3	New parts have been ordered to repair the shaft collars where the shaft joins to the motor gearbox.
5.09	PID10B	Carbon Absorber - LGAC 201A	Running			
5.10	PID10B	Carbon Absorber - LGAC 201B	Running			
5.11	PID10B	Carbon Absorber - LGAC 201C	Running			
<b>6</b>		<b>First Stage FBRs A, 1 &amp; 2</b>				
6.01	PID14	FBR A			2	The FBR was taken offline to inspect and locate any possible discrepancies on the vessel.
6.02	PID14	Separator Tank - 1401				
6.03	PID14	Media Return Pump - P 1401				

Status Codes

Running - Unit is in operation  
 Standby - Spare or duplicate, not currently in operation  
 Maintenance - Out of service for maintenance  
 Off - Not currently needed for use, but can be placed in service

Criticality Codes

1= Critical - Cannot continue with operation until repairs made  
 2= Important - Can still operate safely and in compliance with permits, but risks are increased  
 3= Moderate - Work needs to be performed, but plant can still operate with redundancy that is in place  
 4= Low - Minor repairs that in no way alter the performance of the plant

Sub-System	P&ID	Description	Status <sup>1</sup>	Checked	Criticality <sup>2</sup>	Notes
6.04	PID14	P1401A				
6.05	PID01A	P1401B				
6.06	PID01A	FBR 1	Running			
6.07	PID02A	FBR 2	Running			
6.08	PID01A	First Stage Separator Tank - T2011	Running			
6.09	PID01A	Media Return Pump - P2011	Running		3	The media return pump was reinstalled and put back into service.
6.10	PID01A	First Stage FBR Pump - P1011	Standby			
6.11	PID01A	First Stage FBR Pump - P1012	Running			
6.12	PID01A	First Stage FRB Pump - P101A	Running			
6.13	PID07A	FBR A pH Feed Pump - P71A	Off			
6.14	PID07A	FBR 1 pH Feed Pump - P711	Off			
6.15	PID07A	FBR 2 pH Feed Pump - P712	Off			
6.16	PID07A	FBR A Nutrient (Urea) Feed Pump - P72A	Off			
6.17	PID07A	FBR 1 Nutrient (Urea) Feed Pump - P721	Off			
6.18	PID07A	FBR 2 Nutrient (Urea) Feed Pump - P722	Off			
6.19	PID15	FBR A Nutrient (Phos Acid) Feed Pump - P1520A	Running			
6.20	PID15	FBR 1 Nutrient (Phos Acid) Feed Pump - P1521	Running			
6.21	PID15	FBR 2 Nutrient (Phos Acid) Feed Pump - P1522	Running			
6.22	PID07B	FBR A Electron Donor Assembly Pump - P73A	Running			
6.23	PID07B	FBR 1 Electron Donor Assembly Pump - P731	Running			
6.24	PID07B	FBR 2 Electron Donor Assembly Pump - P732	Running			
<b>7</b>		<b>First Stage FBRs 3 &amp; 4</b>				
7.01	PID01B	FBR 3	Running			
7.02	PID01B	FBR 4	Running		3	A new 2 hp Baldor motor was installed on the bed height control pump to replaced the existing that was worn but still functional.
7.03	PID02B	First Stage Separator Tank - T2012	Running			
7.04	PID01B	Media Return Pump - P2012	Running			
7.05	PID01B	First Stage FBR Pump - P1013	Running			
7.06	PID01B	First Stage FRB Pump - P1014	Running			
7.07	PID01B	First Stage FBR Pump - P102A	Running			
7.08	PID07A	FBR 3 pH Feed Pump - P713	Running			
7.09	PID07A	FBR 4 pH Feed Pump - P714	Running			
7.10	PID07A	FBR 3 Nutrient (Urea) Feed Pump - P723				
7.11	PID07A	FBR 4 Nutrient (Urea) Feed Pump - P 724	Off			

Status Codes

Running - Unit is in operation  
 Standby - Spare or duplicate, not currently in operation  
 Maintenance - Out of service for maintenance  
 Off - Not currently needed for use, but can be placed in service

Criticality Codes

1 = Critical - Cannot continue with operation until repairs made  
 2 = Important - Can still operate safely and in compliance with permits, but risks are increased  
 3 = Moderate - Work needs to be performed, but plant can still operate with redundancy that is in place  
 4 = Low - Minor repairs that in no way alter the performance of the plant

Sub-System	P&ID	Description	Status <sup>1</sup>	Checked	Criticality <sup>2</sup>	Notes
7.12	PID15	FBR 3 Nutrient (Phos Acid) Feed Pump - P1523	Running			
7.13	PID15	FBR 4 Nutrient (Phos Acid) Feed Pump - P1524	Running			
7.14	PID07B	FBR 3 Electron Donor Assembly Pump - P733	Running			
7.15	PID07B	FBR 4 Electron Donor Assembly Pump - P734	Running			
<b>8</b>		<b>Second Stage FBRs 5 &amp; 6</b>				
8.01	PID03A	FBR 5	Running			
8.02	PID03A	FBR 6	Running			
8.03	PID03C	Second Stage Separator Tank - T3011	Running			
8.04	PID03A	Media Return Pump - P3011	Running			
8.05	PID03A	Second Stage FBR Pump - P3015	Running			
8.06	PID03A	Second Stage FBR Pump - P3016	Standby			
8.07	PID03A	Second Stage FBR Pump - P301A	Running			
8.08	PID07A	FBR 5 pH Feed Pump - P715	Off			
8.09	PID07A	FBR 6 pH Feed Pump - P716	Off			
8.1	PID07A	FBR 5 Nutrient (Urea) Feed Pump - P725	Off			
8.11	PID07A	FBR 6 Nutrient (Urea) Feed Pump - P726	Off			
8.12	PID07B	FBR 5 Electron Donor Assembly Pump - P735	Running			
8.13	PID07B	FBR 6 Electron Donor Assembly Pump - P736	Running			
<b>9</b>		<b>Second Stage FBRs 7 &amp; 8</b>				
9.01	PID03B	FBR 7	Running			
9.02	PID03B	FBR 8	Running			
9.03	PID03D	Second Stage Separator Tank - T3012	Running			
9.04	PID03B	Media Return Pump - P3012	Running			
9.05	PID03B	Second Stage FBR Pump - P3017	Running			
9.06	PID03B	Second Stage FBR Pump - P3018	Running			
9.07	PID03B	Second Stage FBR Pump - P302A	Running			
9.08	PID07A	FBR 7 pH Feed Pump - P717	Off			
9.09	PID07A	FBR 8 pH Feed Pump - P718	Off			
9.10	PID07A	FBR 7 Nutrient (Urea) Feed Pump - P727	Off			
9.11	PID07A	FBR 8 Nutrient (Urea) Feed Pump - P728	Off			
9.12	PID07B	FBR 7 Electron Donor Assembly Pump - P737	Running			
9.13	PID07B	FBR 8 Electron Donor Assembly Pump - P738	Running			
<b>10</b>		<b>Aeration and DAF System</b>				
10.01	PID04	Aeration Tank	In operation			
10.02	PID04	Aeration Blower - B401	Running			
10.03	PID04	Biofilter	In operation			
10.04	PID04	Nutrient Solution	Running			

Status Codes

Running - Unit is in operation  
 Standby - Spare or duplicate, not currently in operation  
 Maintenance - Out of service for maintenance  
 Off - Not currently needed for use, but can be placed in service

Criticality Codes

1 = Critical - Cannot continue with operation until repairs made  
 2 = Important - Can still operate safely and in compliance with permits, but risks are increased  
 3 = Moderate - Work needs to be performed, but plant can still operate with redundancy that is in place  
 4 = Low - Minor repairs that in no way alter the performance of the plant

Sub-System	P&ID	Description	Status <sup>1</sup>	Checked	Criticality <sup>2</sup>	Notes
10.05	PID04	Biofilter Sump	Running			
10.06	PID04	Nutrient Pump - P401	Running			
10.07	PID04	Biofilter Sump Pump - P402A	Standby			
10.09	PID04	Biofilter Blower	Running			
10.10	PID05	DAF Pressure Tanks	In operation		2	A new pressure tank was installed due to damage to the old vessel that was at risk.
10.11	PID05	DAF Vessel - D501	Running		2	The vessel was drained and inspected. A patch was welded on a portion of the vessel (not submerged in water). Parts were replaced on the skimmer system to include rubber flaps, rollers and links connecting the chain system.
10.12	PID05	DAF Pressure Pump - P501	Running		2	The pressure pump was taken out to have the gearbox seals replaced and the mechanical seal repaired. This was caused by wear and tear over the years of service.
10.13	PID05	DAF Float Pump - P502	Running			The pump was replaced with the spare pump during the service of the vessel and the old one was taken to the maintenance shop to be rebuilt.
10.14	PID05	DAF Vessel - D551	Running			
10.15	PID05	DAF Pressure Pump - P551	Running			
10.16	PID05	DAF Float Pump - P552	Running			
10.17	PID05	Screw Conveyer Drive	Standby			
10.18	PID05	Skimmer Drive	Running			
<b>11</b>		<b>Pumping System (Old Effluent)</b>				
11.01	PID06	Effluent Tank 601	In operation			
11.02	PID06	Effluent Pump - P601	Running			
11.03	PID06	Effluent Pump - P602	Standby			
<b>12</b>		<b>Sand Filter System</b>				
12.01	PID17	Sand Filter	Running			
12.02	PID17	Filter Reject Tank	In operation			
12.03	PID17	Filter Reject Pump - P1701A	Standby			
12.04	PID17	Filter Reject Pump - P1701B	Running		3	A new mechanical seal was replaced on the pump.
<b>13</b>		<b>Effluent Tank and Pumping</b>				
13.01	PID10C	UV Effluent Tank	Running			
13.02	PID10C	Effluent Booster Pump - P1302A	Running			
13.03	PID10C	Effluent Booster Pump - P1302B	Standby			
13.04	PID10C	Area Around Effluent and North D-1	Running			
<b>14</b>		<b>Solids Collection and Pressing System</b>				
14.01	PID16	Sludge Storage Tank	In operation			

Status Codes

Running - Unit is in operation  
 Standby - Spare or duplicate, not currently in operation  
 Maintenance - Out of service for maintenance  
 Off - Not currently needed for use, but can be placed in service

Criticality Codes

1 = Critical - Cannot continue with operation until repairs made  
 2 = Important - Can still operate safely and in compliance with permits, but risks are increased  
 3 = Moderate - Work needs to be performed, but plant can still operate with redundancy that is in place  
 4 = Low - Minor repairs that in no way alter the performance of the plant



Sub-System	P&ID	Description	Status <sup>1</sup>	Checked	Criticality <sup>2</sup>	Notes
14.02	PID16	Solids Storage Effluent Pump - P1601	Running			
14.03	PID16	Solids Cond. Tank	In operation			
14.04	PID09	Sludge Mixer	Running			
14.05	PID09	Filter Press Pump - P901	Running			
14.06	PID09	Filter Press Pump - P902	Running			
14.07	PID09	West Press	Standby			
14.08	PID09	East Press	Running			
14.09	PID09	Filtrate Tank	In operation			
14.10	PID09	Filtrate Tank Effluent (recycle) Pump - P903	Running			
<b>Chemical Systems</b>						
<b>15</b>	<b>Electron Donor System</b>					
15.01	PID07B	Electron Donor Tank	In operation			
15.02	PID07B	Booster Pump P739A	Running			
15.03	PID07B	Booster Pump P739B	Standby			
17	PID07C	Micro Nutrient System	In operation			
18	PID07C	Hydrogen Peroxide System	In operation			
19	PID07C	De-Foam System	In operation			
20	PID15	Nutrient (Phosphoric Acid) System (Tank only - pumps included in FBRs)	In operation			
21	PID07A	Nutrient (Urea) System (Tank only - pumps included in FBRs)	In operation			
22	PID07A	pH System (Tank and effluent pH feed pump only - other pumps included in FBRs)	In operation			
23	PID07C	Ferric Chloride System	In operation			
24	PID07B	Polymer Systems - DAF	In operation			
25	PID09	Polymer System - Solids Dewatering (2 tanks, 2 centrifugal pumps, mixer, volumetric feeder)	In operation			
<b>Utility Systems</b>						
<b>26</b>	<b>Compressed Air System</b>					
26.01	PID08	West Compressor	Running			
26.02	PID08	East Compressor	Running			
26.03	PID08	O2 Compressor	Running			
26.04	PID08	Compressed Air Receiver Tank	In operation			
26.05	PID08	Air Dryer	Running			
26.06	PID08	Oil Removal Filter	In operation			
26.07	PID08	Particulate Filter	In operation			

Status Codes

Running - Unit is in operation  
 Standby - Spare or duplicate, not currently in operation  
 Maintenance - Out of service for maintenance  
 Off - Not currently needed for use, but can be placed in service

Criticality Codes

1= Critical - Cannot continue with operation until repairs made  
 2= Important - Can still operate safely and in compliance with permits, but risks are increased  
 3= Moderate - Work needs to be performed, but plant can still operate with redundancy that is in place  
 4= Low - Minor repairs that in no way alter the performance of the plant

Sub-System	P&ID	Description	Status <sup>1</sup>	Checked	Criticality <sup>2</sup>	Notes
27	PID16	Oxygen System	In operation			
28		GWETS Plant Controls/ Siemens Controls	In operation			
29		Well Control System/ Allen Bradley Controls	In operation			
30		MCC FBR Pad	In operation			
31		MCC in D-1	In operation			
32		MCC in EQ area	In operation			
<b>Miscellaneous Systems</b>						
33		Operations Office/Network	In operation			
34		Laboratory Analyzers	In operation			
35		Security Systems	In operation			
<b>Shelf Spares</b>						
		Media Return Pump Rebuild Kit	In stock			
		pH Feed Pump	In stock			
		Nutrient Feed Pump	In stock			
		Electron Donor Feed Pump	In stock			
		Phosphoric Acid Feed Pump	In stock			
		Interceptor Well Pumps (4 each)	In stock			
		Seep Well Pump (1 each, same as Athens so total of 2)	In stock			
		Athens Road Well Pump (1 each, same as Seep so total of 2)	In stock			

Status Codes

Running - Unit is in operation  
 Standby - Spare or duplicate, not currently in operation  
 Maintenance - Out of service for maintenance  
 Off - Not currently needed for use, but can be placed in service

Criticality Codes

1= Critical - Cannot continue with operation until repairs made  
 2= Important - Can still operate safely and in compliance with permits, but risks are increased  
 3= Moderate - Work needs to be performed, but plant can still operate with redundancy that is in place  
 4= Low - Minor repairs that in no way alter the performance of the plant