



---

**To:** Nevada Division of Environmental Protection  
Nevada Environmental Response Trust

---

**Cc:** Nevada Environmental Response Trust Stakeholders

---

**From:** Jeff Lambeth, Director of Operations

---

**Date:** January 20, 2017

---

**Subject:** NERT – GWETS Operation Monthly Report – January 2017

---

At the request of the Nevada Environmental Response Trust (Trust), Envirogen Technologies, Inc. (ETI) is providing this summary of the groundwater extraction and treatment system (GWETS) operation and performance during January 2017.

### Summary of GWETS Operation

Envirogen Technologies, Inc. (ETI) mechanically operated the GWETS normally in January 2017. The flow rate to the plant averaged approximately 1,005 gallons per minute (gpm) during January 2017. At the end of the month, the GW-11 Pond volume was at 49.5 million gallons (MG), which would allow 9.0 days of available additional storage in the event of an emergency plant shutdown with continued well field pumping. The water volume stored in the GW-11 Pond increased approximately 6.6 MG from the end of December 2016. Figure 1 in this report depicts the actual GW-11 pond volumes and additional storage available.

The influent perchlorate concentration to the FBR plant averaged 100 mg/L for the month, with a maximum concentration of 110 mg/L. In comparison, the influent perchlorate concentration for the month of December 2016 averaged 96 mg/l, with a maximum concentration of 100 mg/l.

Analytical data indicate that the permitted effluent discharges at GWETS Outfall 001 were within the NPDES permitted numerical discharge limits (Please see Attachment A, prepared by Ramboll Environ).

### Enhanced Operational Metrics

Tables 1 and 2 provide a summary of the current GWETS operational metrics data for flow rates, perchlorate and chromium concentrations, and mass removal. Figure 2 graphically presents historical perchlorate and chromium mass flux information.

### Operational Issues

All routine plant repairs conducted by ETI were performed in accordance with the NERT Perchlorate Treatment System Operations Manual. The following is a list of operational issues and major repairs and/or equipment replaced during this reporting period.

## 1. GW-11

- Upgrade activities at Lift Station 1 required the operators to use the GW-11 pond for influent equalization beginning on January 16<sup>th</sup> at 7:05am with a return to TK-101 equalization the next day at 11:20am, January 17<sup>th</sup>. The plant operators adjusted operations to compensate for the change in influent equalization.

## 2. Biological Plant

There were no significant plant interruptions. There were two unplanned diversions into GW-11 for the month of January and one event that put the biological plant in recycle mode. Below is a description of the short duration events that occurred:

- Effluent Diversion to GW-11 on January 5<sup>th</sup> from 6:00am to 7:20am. The plant effluent was diverted as a precautionary measure due to concerns regarding effluent quality. Effluent discharge to the Las Vegas Wash resumed following laboratory verification of water quality.
- Effluent Diversion to GW-11 on January 30<sup>th</sup> from 1:30pm to 2:33pm. The plant effluent was diverted as a precautionary measure due to concerns regarding effluent quality. Effluent discharge to the Las Vegas Wash resumed following laboratory verification of water quality.
- Recycle mode on January 4<sup>th</sup> from 2:34 pm to 2:46 pm. Loss of communication from the lift stations occurred at 2:34pm on January 4<sup>th</sup> due to a blown fuse in the control panel resulting in water level of the TK-101 Equalization tanks falling below acceptable limits. The plant was put into Recycle mode while the fuse was replaced at 2:46pm.

## 3. Spills

There were no reportable spills in the month of January.

There was one non-reportable spill in the month of January. On Monday January 30, 2017, at approximately 1:00pm, Envirogen informed the Trust it had a failure of an Effluent line valve as part of the "pig launcher" assembly in the EQ area, this put too much pressure on the existing drain line causing it to spray water out of containment. The total volume of treated effluent that spilled to the ground was approximately 50 gallons.

## 4. Maintenance

- Major maintenance performed by ETI in the month included:
  - I. LS#1, IX System – ETI relocated and assisted in calibrating the pressure sensor on the new frack tank.
  - II. TK1, GWTP Feed Tank- Level Transmitter has been replaced by ETI and the Level Alarm - High (LAH) was added to the Auto-dialer system.
  - III. ART1 AWF extraction well - The VFD showed a fault of F0001. The motor/pump were pulled and a damaged wire was discovered. The pigtail and 1.5 hp motor were replaced and the pump was put back online as the lead pump.
  - IV. P5 GWTP – the press pump was removed due to leaking gaskets at the housing. A spare pump was put in place and the repairs were made to the leaking pump. The repaired pump is on the shelf and is ready for service if needed.

- V. LS#1 – the lift station was taken offline to install the new flow meters as a part of the IX upgrade. Once completed the lift station was brought back online with no complications.
  - VI. P502 DAF – the sludge pump was taken offline and to replace a pumping disc. The disc was worn and was reducing the efficiency of the pump.
  - VII. D1 Building – During the removal and placing of 20 yard roll away sludge bins, the locking pin on the door frame was damaged. A new pin was welded on so the door can be secured.
  - VIII. P402 Bio Filter – the sump pump had a faulty seal damaging the motor to the pump. A new pump and motor have been ordered.
  - IX. M3015 FBR 5 – the recycle motor shut down due to high temperature from a damaged bearing. The motor was pulled and a new spare was put in place. The damaged motor was taken to Henderson Electric for repairs.
- Preventative Maintenance completed or being performed by ETI in the month included:
    - I. Sequence Test Alarms – ETI Tested all signals related to the auto plant shutdown sequence.
    - II. PH and ORP online analyzers – ETI Calibrated and Standardized Units with buffer solutions.
    - III. Plant Computer – ETI Generated backup and cleaned the air filters for the computer enclosure.
    - IV. Pond (GW11) Level Sensor – ETI removed and cleaned the sensor and loop checked the signal to the control room.
    - V. D551 DAF vessel – The vessel was drained and inspected for any structural damage including damage moving parts and the wall coating. No issues were discovered.
    - VI. LS3 rotation of buddy wells – The buddy wells were tested and confirmed to be in good working order.
    - VII. Effluent pipeline – The combo/air release valves were inspected along the entire pipeline. No faults or leaks were identified.
    - VIII. T1702 Sand filter Inspection – All accessible parts of the sand filter were inspected. The sand filter requires a more extension inspection of the working components below the water level. The unit was taken offline and is currently draining.

## GWETS Upgrades and Facility Projects

The following is a summary of the initiatives in-progress during the reporting period at the direction of the Trust:

### 1. AP-5 Solids Removal

Tetra Tech continued to move forward with the AP-5 Solids Removal project and completed transfer of the contents of the AP-5 Pond to the tanks. Sediment washing was initiated as the material was transferred to the tank but decant liquids are not expected to be ready for treatment until mid-2017.

### 2. Lift Station #1 upgrades

ETI has completed implementing infrastructure improvements at Lift Station 1 and the addition of an Ion Exchange system in January including final cleanup of punch list items. Record documentation and O&M manual will be completed before the end of Feb 2017. It is anticipated the system will begin operation sometime in February.

### 3. IWF well modifications

A proposal for the IWF has been prepared to address the Trust's desire to improve the flow meter accuracy and installation of VFDs on the extraction pumps. This proposal was submitted by ETI Engineering and is currently under review by the Trust.

### 4. Spill containment enhancements

A proposal for secondary containment modifications has been assembled by ETI Engineering and the Trust approved implementation on February 6th.

### **ECT Audit Findings**

ETI has been addressing the recommendations provided in the Independent Audit of the GWETS performed by ECT. Table 3 summarizes the status of the ECT Audit findings. Progress is reported in the Status column. Updates from the prior reporting period appear in bold, underlined text.

### **Equipment Availability Tracking**

ETI operators continue to update the equipment tracking form on a weekly basis or whenever there is a change in the status of key equipment. During regular site visits, Tetra Tech field personnel verify the entries on the form, including both the operating status and confirmation of the inventory of required shelf spares. The equipment tracking form is included as Attachment B.

### **GWETS Staffing**

ETI continues with 24-hour staffing of the GWETS at the direction of the Trust and continues to follow the security procedures in the Standard Operating Procedures (SOP).

# Tables

---

*Operational Metrics*

Nevada Environmental Response Trust   Groundwater Extraction and Treatment System   Monthly Stakeholder Metrics				
Location ID	Average Flow Rate (gpm)	Perchlorate (mg/L) <sup>4 5</sup>	Chromium (TR) (mg/L) <sup>4 5</sup>	Chromium(VI) (mg/L) <sup>4 5</sup>
SWF Total Extraction <sup>2</sup>	571 <sup>1</sup>	12	0.013	0.00068
AWF Total Extraction <sup>2</sup>	410 <sup>1</sup>	106	0.21	0.21
IWF Total Extraction <sup>2</sup>	66 <sup>1</sup>	794	8.1	7.5
AP Area Total Extraction	4.0	1,760	NA	0.033
GWTP Effluent <sup>3</sup>	81	862	0.24	ND
GW-11 Influent <sup>2</sup>	34	80	0.086	0.057
GW-11 Effluent/ FBR Influent <sup>3</sup>	1005	100	0.074	0.049

## Notes:

TR = Total Recoverable; NA = Not Analyzed; ND = Not detectable above laboratory method detection limit (Chromium (VI) = 0.25 ug/L).

1: Sum of daily average flow for individual wells.

2: Perchlorate and chromium TR sampled monthly, values reported from TestAmerica.

3: Perchlorate, chromium TR and chromium (VI) sampled weekly, values reported from TestAmerica.

4: All concentrations reported are monthly flow weighted averages.

5: ND analytical values are treated as zero values in the flow weighted average calculations.

Nevada Environmental Response Trust   Groundwater Extraction and Treatment System   Monthly Stakeholder Metrics			
Location ID	Perchlorate (lbs/month) <sup>1</sup>	Chromium (TR) (lbs/month) <sup>1</sup>	Chromium (VI) (lbs/month) <sup>1</sup>
SWF Total Extraction	2,632	2.8	0.15
AWF Total Extraction	16,221	32	32
IWF Total Extraction	19,490	200	184
AP Area Total Extraction	2,895	NA	0.05
GWTP Effluent	25,995	7.1	0.00
GW-11 Influent	1,018	1.1	0.73
GW-11 Effluent/FBR Influent	37,689	28	18

## Notes:

TR = Total Recoverable; NA = Not Analyzed.

1: Total mass extracted is calculated from flow weighted average concentration and average flow (see Table 1).

**Table 3 - Status of ECT Audit Recommendations**

<b>LS #1 and Seep Field</b>			
<b>Number</b>	<b>Ranking</b>	<b>Issue Description</b>	<b>Status</b>
1	Priority A	<p>Lift Station #1 should be evaluated for repair and upgrade.</p> <p>a. A high priority should be placed on abandoning and replacement of the flexible hoses and the aging parallel piping at Lift Station #1.</p> <p>b. Lift Station #1 should be re-evaluated to assure that the designs, and the materials of construction, are consistent with the current and future facility needs in full recognition that this operation is likely to continue for a significant period of time.</p>	<p><i>Completed</i> The flexible hoses were replaced as part of the IX Upgrade. Rigid above ground extraction well piping will be replaced following startup of the new IX treatment system.</p> <p><i>During the design of the Lift Station 1 upgrades ETI selected materials of constructed to ensure long-term reliability.</i></p>
2	Priority A	<p>The SWF vaults should be sealed using commercially available sealants used in Industry and wastewater treatment to prevent exfiltration.</p>	<p><i>Completed. ETI inspected all Seep Well Field vaults and sealed all vault penetrations with recommended foam.</i></p>
3	Priority A	<p>The SWF well fields should be inspected and aging wells replaced as practicable. Much of the above grade plumbing is old and unreliable. Also, some of the wells cycle on and off fairly rapidly. This would indicate that the groundwater has been lowered or more likely, the well screens have become fouled, limiting the flow into the well.</p> <p>The local hydrogeology around the rapidly dewatering wells should be analyzed and the wells should be replaced if it is determined that they have become fouled.</p>	<p><i>In Process</i></p> <p><i>The flexible hoses were replaced as part of the IX Upgrade. Rigid above ground extraction well piping will be replaced following startup of the new IX treatment system.</i></p> <p><i>Aquifer evaluation of the SWF is currently ongoing as part of the COP. If necessary, well maintenance activities will be performed to improve well yield.</i></p>
4	Priority A	<p>The Audit Team recommends that ETI consider using a screening process capable of managing a higher solids content to address issues including the Boatmen bug spawns.</p>	<p><i>Closed - This issue occurs twice per year in spring and fall for a few weeks each time. ETI feels this is not necessary in light of future plans for the GW-11 pond, and this issue would be mitigated by those plans. Based on ETI's research, this is a common problem in ponds in the area.</i></p>
5	Priority A	<p>The auditors observed an area where crystals of unknown nature have formed at PC-99 R2/R3. NERT should sample the observed crystals and analyze their composition at the earliest opportunity. The R3 well enclosure had standing water and crystals formed both inside and outside of the well vault. The Audit Team also noted a damp area extending from the R3 vault to about 10 to 15 feet from the enclosure. The Audit Team did not collect samples from the damp area or of the observed crystals. While it is possible that the observed crystals are not perchlorate but rather salts resulting from the extremely hard water in the area, with no data available, caution should be observed.</p>	<p><i>Closed</i></p> <p><i>Crystals were hard water calcium from a leaking flange gasket. This area was cleaned and a new gasket was installed.</i></p> <p><i>NERT collected a soil sample immediately below the salt crystals previously observed on November 18, 2016 for laboratory analysis. During the sampling event NERT discovered that the salt crystals were no longer present on the side of the well vault. Salt crystals in this area tend to be transient in nature. The analytical</i></p>



			<p>results indicate the presence of perchlorate in soil at a concentration of 19 mg/kg. This concentration is below the NDEP's Residential Basic Comparison Level. However, this situation will be further evaluated as part of the Phase 2 Remedial Investigation.</p>
6	Priority B	A detailed inspection of the SWF underground piping should be performed to estimate the remaining useful life.	<p><u>Closed</u> As part of the RI/FS NERT will re-evaluate the SWF and its conveyance piping.</p>
7	Priority B	All abandoned equipment should be removed from the operating areas of the operation.  To be further examined by the Trust.	<p><u>Ongoing</u> Abandoned equipment will be removed as various upgrades occur throughout the plant.</p>
8	Priority B	The access doors at the SWF vaults should be replaced with doors that have modern safety latches and are physically manageable in order to make inspection access easier for the operating staff.	<p><u>Closed</u> ETI does not believe that modifications are necessary to operate the doors. Our staff believe they can safely operate the doors.</p>
9	Priority B	Concurrent with plans to expand the loading of perchlorate to the FBRs, the capacity of the solids handling systems in general, and the DAFs specifically, should be evaluated for upgrade.	<p><u>Closed</u> Completed, both of the DAFs have recently been rehabilitated. The DAF design is more than adequate for the solids generated a full plant load.</p>
10	Priority B	The remaining Penn Valley Double Disc Pumps should be replaced with air-driven double diaphragm pumps as they fail. There should be a review of the need for additional process air to operate the new pumps.	<p><u>In Process</u> Currently ETI is in progress with the pump replacements. <b><u>Three of the four pumps have been replaced with air-driven diaphragm pumps. the remaining Penn Valley Double Disc Pump will be replaced as they fail.</u></b></p>
11	Priority C	A hydraulic analysis should be performed from the discharge port of the variable frequency pumps to the discharge point at the Las Vegas Wash to identify (and eliminate) the areas of highest flow loss.	<p><u>Complete</u> NERT has completed a pipeline flow evaluation and is planning infrastructure upgrades in 2017 to address this issue.</p>
12	Priority C	As the submersible pumps reach the end of their useful life, they should be replaced with more appropriate technology, such as vertical turbine pumps, for increased reliability and ease of service.	<p><u>Complete</u> Vertical turbine pumps were installed as part of the upgrade project for both LS-3 and LS-2.</p>

<b>Job Cal (Maintenance Management Program) and Data Control</b>			
<b>Number</b>	<b>Ranking</b>	<b>Issue Description</b>	<b>Status</b>
1	Priority A	Incorporate all contractor supplied maintenance into the JobCal system.	<p><u>Complete</u> All contractor supplied maintenance activities are being logged in the JobCal computer maintenance management system.</p>
2	Priority B	Improve detail captured in JobCal to include actual level of effort expended in repairs.	<p><u>Complete</u> ETI has worked with the staff to improve the capture of information and detail</p>

			<i>that is logged into the JobCal computer maintenance management system.</i>
3	Priority B	Streamline the management of water quality data to assure accountability.	<u>Complete</u> <i>NERT has established a new data transfer protocol that streamlines the management of water quality data amongst the NERT team members. External accessibility will be improved with the implementation of GWETS/NET</i>
<b>Operations Monitoring</b>			
<b>Number</b>	<b>Ranking</b>	<b>Issue Description</b>	<b>Status</b>
1		Complete conversion of All SCADA systems to a single system – presumably the Siemens system.	<u>In Process</u> <i>The existing Chromium Treatment Plant control system will be replaced when this plant is upgraded or replaced.</i>
2		Incorporate online access and back-up to allow ETI experts to remotely observe and control operations.	<u>In Process</u> <i>GWETS/NET will provide remote access to operational data by NERT and ETI.</i>
<b>Facilities Maintenance</b>			
<b>Number</b>	<b>Ranking</b>	<b>Issue Description</b>	<b>Status</b>
1	Priority A	Infrared electrical surveys should continue to document any potential degradation of electrical and mechanical connections over time and use.	<u>Complete</u> <i>The initial plant survey was completed and actions where needed was taken. The next survey has been incorporated into Job Cal as a re-occurring (PM) event, and is scheduled again for December 2016.</i>
2	Priority A	The electrical grounding within the plant should also be reassessed to make sure that no ground faults are present.	<u>Complete</u> <i>ETI brought in a certified electrician who identified motor skids that were not properly grounded. Since then ETI has installed grounding where it was missing. Based on the site electrical drawings, all known discrepancies have been addressed.</i>
3	Priority A	Limit the length of wiring run from the VFD to the motor/pump units to a maximum of 150 feet.	<u>Complete</u> <i>Any VFD systems to be installed will have a limited cable run, less than 150 feet or based on manufacturers recommendations.</i>
4	Priority A	The motor bearings in motor units operated with VFDs should be lubricated utilizing conductive grease to prevent electrical arching within the motor bearings even if a ground fault occurs.	<u>Complete</u> <i>ETI is currently using conductive grease. The use of conductive grease is currently being logged into Job Cal.</i>
5	Priority A	Utilize full Asset Management Capabilities of Job Cal. As per above,	<u>Complete</u> <i>ETI has further leveraged Job Cal and will continue to expand its use in facility operations.</i>

6	Priority A	Incorporate age of equipment and expected serviceable life for all major equipment.	<u>Complete</u> ETI has further leveraged Job Cal and will continue to expand its use in facility operations.
7	Priority A	Incorporate all contractor supplied maintenance into the JobCal system.	<u>Complete</u> ETI has further leveraged Job Cal and will continue to expand its use in facility operations.
8	Priority B	Improve detail captured in JobCal to include actual level of effort expended in repairs.	<u>Complete</u> ETI has further leveraged Job Cal and will continue to expand its use in facility operations.
<b>Training</b>			
<b>Number</b>	<b>Ranking</b>	<b>Issue Description</b>	<b>Status</b>
1	Priority B	Improved documentation of operator training is recommended. The operators have been taught how to operate the equipment but the documentation and supporting information for training provided and received was lacking – unlike the other training provided on-site.	<u>In Process</u> ETI is continuing to improve new employee training and documentation of said program. The training program and the appropriate documentation will be complete by April 2017.
<b>HazWaste and Recycling</b>			
<b>Number</b>	<b>Ranking</b>	<b>Issue Description</b>	<b>Status</b>
1	Priority B	Install a can puncturer and develop a program to handle aerosol cans to assure that the waste cans are “RCRA empty” at atmospheric pressure.	<u>Complete</u> <b>Complete and on-site.</b>
2	Priority B	Containers storing used oil should be labeled correctly and be moved to a location where they are protected from the elements.	<u>Complete</u>
3	Priority C	As a good management practice for CESQGs obtain an EPA identification number.	<u>Completed by NERT.</u>
4	Priority C	As a good management practice for CESQGs develop and maintain a waste manifest tracking log to manage all of the shipping and receiving manifests for all waste shipments.	<u>Completed by NERT</u>
5		Continue to manage universal waste per the universal waste requirements.	<u>Complete and Ongoing</u>
6	Priority C	Develop a more concise chemical inventory with annual capacities and usages for all applicable chemicals.	<u>In Progress</u> <u>All chemicals are inventoried each month.</u> <u>Usage of each chemical is logged into the HACH Wims Data Management software.</u>
7	Priority C	An applicability study should be completed to determine if the facility is subject to TRI Form R reporting.	<u>Closed</u> After review, ETI does not see the need for this study and is in complete compliance with all reporting currently required.

Notes:

Changes in activity status from the prior month are displayed in the Status column with **bold, underlined font.**

# Figures

---

*Operational Metrics*





Figure 2 - Historical Perchlorate Mass Flux



# Attachment A

---

*NPDES Tracking Sheet (Prepared by ENVIRON)*

Treated Effluent at Outfall 001																			
Continuous		Daily Samples, composited weekly		Weekly Grab Samples										Weekly, collected separately			Quarterly		
Flow Rate		Perchlorate		pH	Hexavalent Chromium	Total Chromium	Manganese	Total Iron	Total Inorganic Nitrogen (TIN)	Total Suspended Solids (TSS)		Total Ammonia as N		Total Phosphorus as P		BOD <sub>5</sub> (inhibited)			Total Dissolved Solids (TDS)
30-Day Avg. (MGD)	Daily Maximum (MGD)	30-Day Avg. (µg/L)	30-Day Avg. (lbs/day)	Daily Min. (S.U.)	Daily Max. (S.U.)	Daily Max. (µg/L)	Daily Max. (µg/L)	Daily Max. (µg/L)	Daily Max. (mg/L)	Daily Max. (mg/L)	Daily Max. (mg/L)	30-Day Avg. (lbs/day)	30-Day Avg. (lbs/day)	30-Day Avg. (lbs/day)	30-Day Avg. (lbs/day)	30-Day Avg. (mg/L)	Daily Max. (mg/L)	30-Day Avg. (lbs/day)	Daily Max. (mg/L)
2.52	2.88	18	0.38	6.5	9.0	10	100	5,000	10,000	20	135	2,839	20*	10*	25	40	525	8,000	
January 2017	1.38	1.42	1.3	0.015	6.76	7.13	0.125	30	510	9,600	0.60	62	390	4.4	1.0	2.4	4.3	27	5,400
February 2017	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA

Daily Grab Sample Dates	Composite Sample Date	µg/L	lbs/day	Sample Date	S.U.	µg/L	µg/L	µg/L	µg/L	mg/L	mg/L	lbs/day	mg/L	lbs/day	mg/L	lbs/day	Sample Date	mg/L	lbs/day	Sample Date	mg/L		
1/1 - 1/7	1/7/2017	ND (<2.5)	1.3	0.014	1/3/2017	6.76	ND (<0.25)	8.0	280	3,100	ND (<0.50)	26	300	--	0.35	4.0	--	0.046	0.53	1/4/2017	2.2	25	
1/8 - 1/14	1/14/2017	ND (<2.5)	1.3	0.015	1/11/2017	7.03	ND (<0.25)	30	410	9,600	0.60	62	728	--	0.60	7.0	--	0.13	1.5	1/11/2017	ND (<0.50)	0.25	2.9
1/15 - 1/21	1/21/2017	ND (<2.5)	1.3	0.015	1/16/2017	7.13	ND (<0.25)	17	510	3,400	ND (<0.50)	27	313	--	0.23	2.7	--	0.078	0.91	1/18/2017	4.3	50	
1/22 - 1/28	1/28/2017	NA	NA	NA	1/24/2017	6.89	ND (<0.25)	29	480	3,100	ND (<0.50)	22	236	--	0.37	4.0	--	0.079	0.85	1/25/2017	2.9	31	
1/29 - 2/4	2/4/2017	NA	NA	NA	1/30/2017	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	2/1/2017	NA	NA	
					2/6/2016	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	2/8/2017	NA	NA	

Note: All analytical responsibilities are performed by TestAmerica Laboratories, Inc. (TestAmerica) in Irvine, California, unless otherwise indicated.  
 NA = Not Available To Date  
 ND = Not Detected above laboratory reporting limit; concentration in adjacent cell to right is one-half the reporting limit (per Permit condition)  
 -- = Analyte detected; see column adjacent to right  
 \* Total phosphorus discharge limitation of 10 lbs/day applies between March 1 and October 31; Ammonia discharge limitation of 20 lbs/day applies between April 1 and September 30; no limits apply the rest of the year.  
 Last Updated: February 10, 2017



# Attachment B

---

*Equipment Tracking Form*

Sub-System	P&ID	Description	Status <sup>1</sup>	Checked	Criticality <sup>2</sup>	Notes
<b>Main Plant Equipment</b>						
<b>1 Seep Wells and Lift Station 1</b>						
1.01		Seep Well Field, 9 wells	Running			
1.02		Lift Station 1 Lift Pump A	Running		3	The packing was replaced as it was showing signs of wear.
1.03		Lift Station 1 Lift Pump B	Standby			
1.04		Area in and around Lift Station 1	Running		1	The liftstation was taken down to change piping and install the new flowmeters for the IX and the liftstation.
<b>2 Athens Road Wells and Lift Station 3</b>						
2.01		Athens Road Well Field, 9 wells	Running		2	A new Franklin 1.5 hp motor was installed as well as new electrical connections. The wiring was frayed causing the VFD to short to ground.
2.02		Lift Station 3 Lift Pump A	Standby			
2.03		Lift Station 3 Lift Pump B	Running			
2.04		Area in and around Lift Station 3	Running			
<b>3 Lift Station 2 and Transmission Pipelines</b>						
3.01		Influent Pipeline	In operation			
3.02		Effluent Pipeline	Running			
3.03		Lift Station 2 Lift Pump A	Running			
3.04		Lift Station 2 Lift Pump B	Standby			
3.05		Area in and around Lift Station 2	Running			
<b>4 Interceptor Wells and Cr Treatment Plant</b>						
4.01		IWF Well Field, 30 wells	Running			
4.02		Ferrous Sulfate Feed System	Running			
4.03		Polymer Feed System	Running			
4.04		Clarifier	In operation			
4.05		Filter Press	Running		3	The 1 1/2" pump was replaced with a rebuilt so the pump could have the gaskets replaced.
4.06		GWTP Effluent Tank	In operation		3	New callout alarms were added to the program as added precautionary measures.
4.07		Interceptor Booster Pump A	Running			
4.08		Interceptor Booster Pump B	Standby			
4.09		Area In And Around GWTP	Running		2	A new level sensor was installed on the level tank.
<b>5 Equalization Area and GW-11 Pond</b>						
5.01	PID10A	Pond GW-11	In operation			
5.02	PID10A	Pond Water Pump - P101A	Running			
5.03	PID10A	Pond Water Pump - P101B	Standby			

Status Codes

Running - Unit is in operation  
 Standby - Spare or duplicate, not currently in operation  
 Maintenance - Out of service for maintenance  
 Off - Not currently needed for use, but can be placed in service

Criticality Codes

1 = Critical - Cannot continue with operation until repairs made  
 2 = Important - Can still operate safely and in compliance with permits, but risks are increased  
 3 = Moderate - Work needs to be performed, but plant can still operate with redundancy that is in place  
 4 = Low - Minor repairs that in no way alter the performance of the plant

Sub-System	P&ID	Description	Status <sup>1</sup>	Checked	Criticality <sup>2</sup>	Notes
5.04	PID10A	Equalization Tanks	In operation			
5.05	PID10A	Area in and Around EQ	In operation			
5.06	PID10A	Raw Water Feed Pump - P102A	Standby			
5.07	PID10A	Raw Water Feed Pump - P102B	Running			
5.08	PID10A	F-101 Filters	Running			
5.09	PID10B	Carbon Absorber - LGAC 201A	Running			
5.10	PID10B	Carbon Absorber - LGAC 201B	Running			
5.11	PID10B	Carbon Absorber - LGAC 201C	Running			
<b>6</b>		<b>First Stage FBRs A, 1 &amp; 2</b>				
6.01	PID14	FBR A				
6.02	PID14	Separator Tank - 1401				
6.03	PID14	Media Return Pump - P 1401				
6.04	PID14	P1401A				
6.05	PID01A	P1401B				
6.06	PID01A	FBR 1	Running			
6.07	PID02A	FBR 2	Running			
6.08	PID01A	First Stage Separator Tank - T2011	Running			
6.09	PID01A	Media Return Pump - P2011	Running			
6.10	PID01A	First Stage FBR Pump - P1011	Standby			
6.11	PID01A	First Stage FBR Pump - P1012	Running			
6.12	PID01A	First Stage FRB Pump - P101A	Running			
6.13	PID07A	FBR A pH Feed Pump - P71A	Off			
6.14	PID07A	FBR 1 pH Feed Pump - P711	Off			
6.15	PID07A	FBR 2 pH Feed Pump - P712	Off			
6.16	PID07A	FBR A Nutrient (Urea) Feed Pump - P72A	Off			
6.17	PID07A	FBR 1 Nutrient (Urea) Feed Pump - P721	Off			
6.18	PID07A	FBR 2 Nutrient (Urea) Feed Pump - P722	Off			
6.19	PID15	FBR A Nutrient (Phos Acid) Feed Pump - P1520A	Running			
6.20	PID15	FBR 1 Nutrient (Phos Acid) Feed Pump - P1521	Running			
6.21	PID15	FBR 2 Nutrient (Phos Acid) Feed Pump - P1522	Running			
6.22	PID07B	FBR A Electron Donor Assembly Pump - P73A	Running			
6.23	PID07B	FBR 1 Electron Donor Assembly Pump - P731	Running			
6.24	PID07B	FBR 2 Electron Donor Assembly Pump - P732	Running			
<b>7</b>		<b>First Stage FBRs 3 &amp; 4</b>				
7.01	PID01B	FBR 3	Running			
7.02	PID01B	FBR 4	Running			
7.03	PID02B	First Stage Separator Tank - T2012	Running			

Status Codes

Running - Unit is in operation  
 Standby - Spare or duplicate, not currently in operation  
 Maintenance - Out of service for maintenance  
 Off - Not currently needed for use, but can be placed in service

Criticality Codes

1 = Critical - Cannot continue with operation until repairs made  
 2 = Important - Can still operate safely and in compliance with permits, but risks are increased  
 3 = Moderate - Work needs to be performed, but plant can still operate with redundancy that is in place  
 4 = Low - Minor repairs that in no way alter the performance of the plant

Sub-System	P&ID	Description	Status <sup>1</sup>	Checked	Criticality <sup>2</sup>	Notes
7.04	PID01B	Media Return Pump - P2012	Running		2	The old media pumping system is in the process of being replaced with an educting system.
7.05	PID01B	First Stage FBR Pump - P1013	Running			
7.06	PID01B	First Stage FRB Pump - P1014	Running			
7.07	PID01B	First Stage FBR Pump - P102A	Running			
7.08	PID07A	FBR 3 pH Feed Pump - P713	Running			
7.09	PID07A	FBR 4 pH Feed Pump - P714	Running			
7.10	PID07A	FBR 3 Nutrient (Urea) Feed Pump - P723				
7.11	PID07A	FBR 4 Nutrient (Urea) Feed Pump - P 724	Off			
7.12	PID15	FBR 3 Nutrient (Phos Acid) Feed Pump - P1523	Running			
7.13	PID15	FBR 4 Nutrient (Phos Acid) Feed Pump - P1524	Running			
7.14	PID07B	FBR 3 Electron Donor Assembly Pump - P733	Running			
7.15	PID07B	FBR 4 Electron Donor Assembly Pump - P734	Running			
<b>8</b>		<b>Second Stage FBRs 5 &amp; 6</b>				
8.01	PID03A	FBR 5	Running			
8.02	PID03A	FBR 6	Running			
8.03	PID03C	Second Stage Separator Tank - T3011	Running			
8.04	PID03A	Media Return Pump - P3011	Running			
8.05	PID03A	Second Stage FBR Pump - P3015	Running			
8.06	PID03A	Second Stage FBR Pump - P3016	Standby			
8.07	PID03A	Second Stage FBR Pump - P301A	Running			
8.08	PID07A	FBR 5 pH Feed Pump - P715	Off			
8.09	PID07A	FBR 6 pH Feed Pump - P716	Off			
8.1	PID07A	FBR 5 Nutrient (Urea) Feed Pump - P725	Off			
8.11	PID07A	FBR 6 Nutrient (Urea) Feed Pump - P726	Off			
8.12	PID07B	FBR 5 Electron Donor Assembly Pump - P735	Running			
8.13	PID07B	FBR 6 Electron Donor Assembly Pump - P736	Running			
<b>9</b>		<b>Second Stage FBRs 7 &amp; 8</b>				
9.01	PID03B	FBR 7	Running			
9.02	PID03B	FBR 8	Running			
9.03	PID03D	Second Stage Separator Tank - T3012	Running			
9.04	PID03B	Media Return Pump - P3012	Running			
9.05	PID03B	Second Stage FBR Pump - P3017	Running			
9.06	PID03B	Second Stage FBR Pump - P3018	Running			
9.07	PID03B	Second Stage FBR Pump - P302A	Running			
9.08	PID07A	FBR 7 pH Feed Pump - P717	Off			
9.09	PID07A	FBR 8 pH Feed Pump - P718	Off			

Status Codes

Running - Unit is in operation  
 Standby - Spare or duplicate, not currently in operation  
 Maintenance - Out of service for maintenance  
 Off - Not currently needed for use, but can be placed in service

Criticality Codes

1 = Critical - Cannot continue with operation until repairs made  
 2 = Important - Can still operate safely and in compliance with permits, but risks are increased  
 3 = Moderate - Work needs to be performed, but plant can still operate with redundancy that is in place  
 4 = Low - Minor repairs that in no way alter the performance of the plant

Sub-System	P&ID	Description	Status <sup>1</sup>	Checked	Criticality <sup>2</sup>	Notes
9.10	PID07A	FBR 7 Nutrient (Urea) Feed Pump - P727	Off			
9.11	PID07A	FBR 8 Nutrient (Urea) Feed Pump - P728	Off			
9.12	PID07B	FBR 7 Electron Donor Assembly Pump - P737	Running			
9.13	PID07B	FBR 8 Electron Donor Assembly Pump - P738	Running			
<b>10</b>		<b>Aeration and DAF System</b>				
10.01	PID04	Aeration Tank	In operation			
10.02	PID04	Aeration Blower - B401	Running		4	A new belt was installed on the blower.
10.03	PID04	Biofilter	In operation			
10.04	PID04	Nutrient Solution	Running			
10.05	PID04	Biofilter Sump				
10.06	PID04	Nutrient Pump - P401	Running			
10.07	PID04	Biofilter Sump Pump - P402A	Standby		2	The pump and motor seized due to wear and tear. A new pump is order as well as a level indicator
10.09	PID04	Biofilter Blower	Running			
10.10	PID05	DAF Pressure Tanks	In operation			
10.11	PID05	DAF Vessel - D501	Running			
10.12	PID05	DAF Pressure Pump - P501	Running			
10.13	PID05	DAF Float Pump - P502	Running			
10.14	PID05	DAF Vessel - D551	Running			
10.15	PID05	DAF Pressure Pump - P551	Running			
10.16	PID05	DAF Float Pump - P552	Running		3	The pump was removed and replaced with the shelf spare.
10.17	PID05	Screw Conveyer Drive	Standby			
10.18	PID05	Skimmer Drive	Running			
<b>11</b>		<b>Pumping System (Old Effluent)</b>				
11.01	PID06	Effluent Tank 601	In operation			
11.02	PID06	Effluent Pump - P601	Running			
11.03	PID06	Effluent Pump - P602	Standby			
<b>12</b>		<b>Sand Filter System</b>				
12.01	PID17	Sand Filter			3	The sandfilter was taken offline due to the coupling boot failing. The boot has been ordered.
12.02	PID17	Filter Reject Tank	In operation			
12.03	PID17	Filter Reject Pump - P1701A	Standby			
12.04	PID17	Filter Reject Pump - P1701B	Running			
<b>13</b>		<b>Effluent Tank and Pumping</b>				
13.01	PID10C	UV Effluent Tank	Running			
13.02	PID10C	Effluent Booster Pump - P1302A	Running			
13.03	PID10C	Effluent Booster Pump - P1302B	Standby			

Status Codes

Running - Unit is in operation  
 Standby - Spare or duplicate, not currently in operation  
 Maintenance - Out of service for maintenance  
 Off - Not currently needed for use, but can be placed in service

Criticality Codes

1= Critical - Cannot continue with operation until repairs made  
 2= Important - Can still operate safely and in compliance with permits, but risks are increased  
 3= Moderate - Work needs to be performed, but plant can still operate with redundancy that is in place  
 4= Low - Minor repairs that in no way alter the performance of the plant

Sub-System	P&ID	Description	Status <sup>1</sup>	Checked	Criticality <sup>2</sup>	Notes
13.04	PID10C	Area Around Effluent and North D-1	Running			
<b>14</b>		<b>Solids Collection and Pressing System</b>				
14.01	PID16	Sludge Storage Tank	In operation			
14.02	PID16	Solids Storage Effluent Pump - P1601	Running			
14.03	PID16	Solids Cond. Tank	In operation			
14.04	PID09	Sludge Mixer	Running			
14.05	PID09	Filter Press Pump - P901	Running			
14.06	PID09	Filter Press Pump - P902	Running			
14.07	PID09	West Press	Standby			
14.08	PID09	East Press	Running			
14.09	PID09	Filtrate Tank	In operation			
14.10	PID09	Filtrate Tank Effluent (recycle) Pump - P903	Running			
		<b>Chemical Systems</b>				
<b>15</b>		<b>Electron Donor System</b>				
15.01	PID07B	Electron Donor Tank	In operation			
15.02	PID07B	Booster Pump P739A	Running			
15.03	PID07B	Booster Pump P739B	Standby			
<b>17</b>	PID07C	Micro Nutrient System	In operation			
<b>18</b>	PID07C	Hydrogen Peroxide System	In operation			
<b>19</b>	PID07C	De-Foam System	In operation			
<b>20</b>	PID15	Nutrient (Phosphoric Acid) System (Tank only - pumps included in FBRs)	In operation			
<b>21</b>	PID07A	Nutrient (Urea) System (Tank only - pumps included in FBRs)	In operation			
<b>22</b>	PID07A	pH System (Tank and effluent pH feed pump only - other pumps included in FBRs)	In operation			
<b>23</b>	PID07C	Ferric Chloride System	In operation			
<b>24</b>	PID07B	Polymer Systems - DAF	In operation			
<b>25</b>	PID09	Polymer System - Solids Dewatering (2 tanks, 2 centrifugal pumps, mixer, volumetric feeder)	In operation			
		<b>Utility Systems</b>				
<b>26</b>		<b>Compressed Air System</b>				
26.01	PID08	West Compressor	Running		3	IR came out to perform the routine maintenance on the units. There are no signs of potential failure.
26.02	PID08	East Compressor	Running			
26.03	PID08	O2 Compressor	Running			

Status Codes

Running - Unit is in operation  
 Standby - Spare or duplicate, not currently in operation  
 Maintenance - Out of service for maintenance  
 Off - Not currently needed for use, but can be placed in service

Criticality Codes

1 = Critical - Cannot continue with operation until repairs made  
 2 = Important - Can still operate safely and in compliance with permits, but risks are increased  
 3 = Moderate - Work needs to be performed, but plant can still operate with redundancy that is in place  
 4 = Low - Minor repairs that in no way alter the performance of the plant

Sub-System	P&ID	Description	Status <sup>1</sup>	Checked	Criticality <sup>2</sup>	Notes
26.04	PID08	Compressed Air Receiver Tank	In operation			
26.05	PID08	Air Dryer	Running			
26.06	PID08	Oil Removal Filter	In operation			
26.07	PID08	Particulate Filter	In operation			
27	PID16	Oxygen System	In operation			
28		GWETS Plant Controls/ Siemens Controls	In operation			
29		Well Control System/ Allen Bradley Controls	In operation			
30		MCC FBR Pad	In operation			
31		MCC in D-1	In operation			
32		MCC in EQ area	In operation			
<b>Miscellaneous Systems</b>						
33		Operations Office/Network	In operation			
34		Laboratory Analyzers	In operation			
35		Security Systems	In operation			
<b>Shelf Spares</b>						
		Media Return Pump Rebuild Kit	In stock			
		pH Feed Pump	In stock			
		Nutrient Feed Pump	In stock			
		Electron Donor Feed Pump	In stock			
		Phosphoric Acid Feed Pump	In stock			
		Interceptor Well Pumps (4 each)	In stock			Motors have been received and the shelves are stocked sufficiently.
		Seep Well Pump (1 each, same as Athens so total of 2)	In stock			
		Athens Road Well Pump (1 each, same as Seep so total of 2)	In stock			Spares are on the shelf.

Status Codes

Running - Unit is in operation  
 Standby - Spare or duplicate, not currently in operation  
 Maintenance - Out of service for maintenance  
 Off - Not currently needed for use, but can be placed in service

Criticality Codes

1= Critical - Cannot continue with operation until repairs made  
 2= Important - Can still operate safely and in compliance with permits, but risks are increased  
 3= Moderate - Work needs to be performed, but plant can still operate with redundancy that is in place  
 4= Low - Minor repairs that in no way alter the performance of the plant