

NDEP # 071212-01



**Complaint/Spill Report Form**

**Report Date:** 12/12/2007 **Report Time:** 1630

State of Nevada

**Incident Date:** 12/12/2007 **Incident Time:** 1615

Telephone: (888) 331-6337

Fax: (775) 687-8335

**Do You Want to Remain Anonymous?**

**Reporting Person/Agency** Nevada Pick-a-Part/ Steve Burke

**Address:** 110 W. Rolly **Phone:** 702-528-3125

**City:** Henderson **State:** NV **Zip:** 89011

**Discharger/Owner/Operator of Facility:** Nevada Pick-A-Part

**Address:** 110 W. Rolly

**City:** Henderson **State:** NV **Zip:** 89011

**Contact Person:** Steve Burke **Phone:** 702-528-3125

**Location of Complaint/Spill:** various locations at Rolly address, site of car dismantling and parts sales operation.

**City:** Henderson **State:** NV **County:** Clark

**Township:**        **Range:**        **Section:**        **Q,Q2:**        **Mile Marker:**       

**Type of Material Discovered:** oil, TPH

**Concentration (% , ppm, ppb):**       

**Quantity Found:** >3cy **Media Affected:** soil

**Cause of Complaint/Spill:** historic leaking of car crankcases, etc. in various locations on site.

**Remedial Action Taken:** See Shannon Harbour for details; she should be case officer also.

**Oversight/Enforcement:** BCA LV (Remediation) Todd Croft & James Dotchin, via e-mail

**cc:**       

**cc:**       

**Comments:** This is another case of many deminimis areas of contaminated soil that cumulatively add up to >3cy.

**Report Taken By:** Jeryl Gardner