

April 25, 2012

Compliance Coordinator  
State of Nevada Division of Environmental Protection  
Bureau of Water Pollution Control  
901 South Stewart Street, Suite 4001  
Carson City, Nevada 89701-5249


Subject: Permit NEV2001515 Discharge Monitoring Reports (DMRs) – 1<sup>st</sup> Quarter 2012  
Nevada Environmental Response Trust Site; Henderson, Nevada

The Nevada Environmental Response Trust (NERT) maintains Permit #NEV2001515 which covers the synthetically double-lined ponds GW-11 and AP-5. No water was discharged directly to a receiving water body from either GW-11 or AP-5 pond. However, water from both GW-11 and AP-5 ponds (along with other groundwater sources) was treated for perchlorate removal and discharged under the authority of NPDES permit NV0023060. The attached DMRs, (Attachment 1) and accompanying tables provide the operational information on the ponds. Included with this correspondence are the January, February and March 2012 DMRs.

Please note that AP-5 pond's top liner has a tear at the top edge of the pond, which is well above the liquid level of the pond contents. The pond is a synthetically double-lined pond and there is no evidence that the underlying liner has been compromised. In addition, the monitoring well which is located between the top liner and the bottom liner to collect any water which accumulates between the liners, has not shown evidence of water presence. The split top liner has been sandbagged to prevent a strong breeze from lifting the edges and the top liner tear will be closely monitored.

Should you have any questions concerning this report, please contact Susan Crowley at (702) 592-7727 (cell) or e-mail [smcrowley@cox.net](mailto:smcrowley@cox.net).

Sincerely,



Allan DeLorme, P.E.  
Managing Principal

Attachment

cc: Please see attached distribution sheet