
FIGURE 24
LOWER PONDS WELL LINE PERCHLORATE CONCENTRATION SECTION GRAPH



ERRATA to Annual Remedial Performance Report for Chromium and Perchlorate Tronox LLC, Henderson, Nevada