



DRAFT

LEGEND

- #32 LOU Boundary
 - ⊕ Phase A Sample Location (2006)
 - Phase B Sample Location (2008-2009)
 - Perchlorate Not Detected Above BCL
 - Perchlorate Detected Above BCL
 - dup Duplicate
- Values in bold are greater than BCL
BCL for Perchlorate = 795 mg/kg
- | | |
|-------------------|--------------------------|
| 0.5' : 9.4 | Result Above BCL (mg/kg) |
| 10' : <0.0019 | Result (mg/kg) |
| 30' : <0.0027 | Result (mg/kg) |
- Sample Depth (feet)

Note: Data Shown in Areas III and IV Not Validated.

Grid: Stateplane, Nevada East, NAD83, Feet
Base Aerial Photo from PBS&J, October 2006

PLATE NUMBER:
1-6
SHEET NUMBER:
1

AREAS I, II, III, AND IV SOIL PERCHLORATE RESULTS EXCEEDING BCLS
Tronox Facility
Henderson, Nevada

SCALE: 1" = 300'	DATE: 01/27/10	PROJECT NUMBER: 2027.01
---------------------	-------------------	----------------------------

DESIGNED BY:		REVISIONS	
NO.:	DESCRIPTION:	DATE:	BY:

northgate
environmental management, inc.
TRONOX <http://www.ngem.com>