



May 12, 2011

Mr. John Pekala
ENVIRON International Corporation
560 West Lake Mead Parkway
Henderson, Nevada 89015

Regarding: *Final Visual Inspection – Pipe Abatement RZ-D-10A, Western Area*
Nevada Environmental Response Trust
560 West Lake Mead Parkway
Henderson, Nevada 89015
Project No. - CON111106

Dear Mr. Pekala,

Logistical Solutions (LoSo) is pleased to provide ENVIRON International Corporation this *Letter Report for Final Visual Inspection of the Pipe Abatement in RZ-D-10A, Western Area* conducted for the Nevada Environmental Response Trust site located at 560 West Lake Mead Parkway in Henderson, Nevada. The purpose of the final visual inspection was to identify, within reason, the presence and location of potential asbestos-containing materials (ACMs) within the regulated control zones of Remediation Zone RZ-D-10A, Western Area (project area).

Earth Resource Group excavated and abated 2 four-inch-diameter metal pipes containing pipe wrap that were approximately 214 feet and 14 feet in length on May 10, 2011. The attached site plan depicts the general location of the piping that was removed from RZ-D-10A, Western Area.

Visual Site Inspection

On May 10, 2011, Mr. Ty L. Salazar of LoSo was contacted by Steve Schafer of Earth Resource Group to conduct a final visual clearance inspection of the regulated asbestos zone located in RZ-D-10A of the project area. Mr. Salazar performed a visual inspection on May 10, 2011 of the regulated asbestos zone upon the completion of the asbestos abatement activities that were performed by Earth Resource Group. The regulated asbestos zone was assessed for signs of visible ACM debris. Asbestos and/or asbestos containing debris was not observed during the inspection of the regulated asbestos zone.

The visual inspection was conducted in a manner consistent with the recommendations specified in the American Society for Testing and Materials (ASTM) E1368-05e1 standard. This report applies only to the subject areas at the time of our inspection.

Limitations

This report has been prepared for the exclusive use of ENVIRON International Corporation, as it applies to the subject regulated asbestos zone at the project area. Logistical Solutions, LLC is not responsible for

any claims and damages associated with interpretation of available information. This assessment should not be regarded as a guarantee that future exposure to the airborne asbestos fibers will not occur.

Our services were performed in accordance with the generally accepted standard of practice at the time this report was written. No warranty, expressed or implied, is intended.

LoSo appreciates being of service to ENVIRON International Corporation on this project. If you have any questions or require additional information, please contact us at (702) 596-2021.


Sincerely,

Logistical Solutions, LLC



Ty L. Salazar, CEM, OHST
Operations Manager
NV Asbestos Consultant No. IM-1413

Attachment



Aerial View - Tronox Asbestos Wrapped Pipe Abatement
Map by Earth Resource Group
AWP4 - 36° 2'54.84" N, 115° 0'27.00" W
Area was visually cleared May 10, 2011.