



June 30, 2011

Mr. John Pekala
ENVIRON International Corporation
560 West Lake Mead Parkway
Henderson, Nevada 89015

Regarding: ***Final Visual Inspection***
 Soil Abatement within RZ-E-06 Culvert
 Nevada Environmental Response Trust
 560 West Lake Mead Parkway
 Henderson, Nevada 89015
 Project No. - CON111106

Dear Mr. Pekala,

Logistical Solutions (LoSo) is pleased to provide ENVIRON International Corporation this *Letter Report for Final Visual Inspection of the Soil Abatement within RZ-E-06 Culvert* conducted for the Nevada Environmental Response Trust site located at 560 West Lake Mead Parkway in Henderson, Nevada. The purpose of the final visual inspection was to identify, within reason, the presence and location of potential asbestos-containing materials (ACMs) within the regulated control zone located with Remediation Zone RZ-E-06 (project area).

On May 20, 2011 to May 22, 2011, Earth Resource group excavated soil from a Beta Ditch culvert until no visual evidence ACM was encountered. The attached site plan depicts the general location of the abatement work area and location of the soil that was removed.

Visual Site Inspection

On June 22, 2011, Mr. Kristopher Everett of LoSo was contacted by Steve Schafer of Earth Resource Group to conduct a final visual clearance inspection of the regulated asbestos zone. Mr. Everett performed a visual inspection on the same day he was contacted by Mr. Schafer of the regulated asbestos zone. The regulated asbestos zone was assessed for signs of visible ACM debris. Asbestos and/or asbestos containing debris was not observed during the inspection of the regulated asbestos zone.

The visual inspection was conducted in a manner consistent with the recommendations specified in the American Society for Testing and Materials (ASTM) E1368-05^{e1} standard. This report applies only to the subject areas at the time of our inspection.

Limitations


This report has been prepared for the exclusive use of ENVIRON International Corporation, as it applies to the subject regulated asbestos zone at the project area. Logistical Solutions, LLC is not responsible for any claims and damages associated with interpretation of available information. This assessment should not be regarded as a guarantee that future exposure to the airborne asbestos fibers will not occur.

Our services were performed in accordance with the generally accepted standard of practice at the time this report was written. No warranty, expressed or implied, is intended.

LoSo appreciates being of service to ENVIRON International Corporation on this project. If you have any questions or require additional information, please contact us at (702) 596-2021.

Sincerely,

Logistical Solutions, LLC



Kristopher Everett, CEM
Project Manager
NV Asbestos Consultant No. IM-1569



Ty L. Salazar, CEM, OHST
Operations Manager
NV Asbestos Consultant No. IM-1413


Attachment



LEGEND

N

Abatement Work Area



Approximate Scale: 1 inch ~ 56 feet



SITE PLAN

Nevada Environmental Response Trust
Remediation Zone RZ-E-06

Project Number
CON111106

