

August 5, 2011

Mr. John Pekala ENVIRON International Corporation 560 West Lake Mead Parkway Henderson, Nevada 89015

Regarding: Final Visual Inspection RZ-C Soil Stockpile Area (Fenced Area) Nevada Environmental Response Trust 560 West Lake Mead Parkway Henderson, Nevada 89015 Project No. - CON111106

Dear Mr. Pekala,

Logistical Solutions (LoSo) is pleased to provide ENVIRON International Corporation this *Letter Report for Final Visual Inspection of the RZ-C Soil Stockpile Area* conducted for the Nevada Environmental Response Trust site located at 560 West Lake Mead Parkway in Henderson, Nevada. The purpose of the final visual inspection was to identify, within reason, the presence and location of potential asbestos- containing materials (ACMs) that were stockpiled within a regulated control zone located within a fenced area between Remediation Zones RZ-C-15 and RZ-C-24 (project area).

Earth Resource Group excavated soil and debirs from several adjacent RZ-C locations during asbestos abatement activities. The materials excavated from these areas were stockpiled within the fenced area between RZ-C-15 and RZ-C-24. The stockpile was subsequently removed on July 30, 2011. The attached site plan depicts the general location of the stockpile control area.

## Visual Site Inspection

On July 30, 2011, Mr. Kristopher Everett of LoSo was contacted by Steve Schafer of Earth Resource Group to conduct a final visual clearance inspection of the regulated asbestos zone. Mr. Everett performed a visual inspection on the same day he was contacted by Mr. Schafer of the regulated asbestos zone. The regulated asbestos zone was assessed for signs of visible ACM debris. Asbestos and/or asbestos containing debris were not observed during the inspection of the regulated asbestos zone.

The visual inspection was conducted in a manner consistent with the recommendations specified in the American Society for Testing and Materials (ASTM) E1368-05<sup> $\epsilon$ 1</sup> standard. This report applies only to the subject areas at the time of our inspection.

## **Limitations**

This report has been prepared for the exclusive use of ENVIRON International Corporation, as it applies to the subject regulated asbestos zone at the project area. Logistical Solutions, LLC is not responsible for any claims and damages associated with interpretation of available information. This assessment should not be regarded as a guarantee that future exposure to the airborne asbestos fibers will not occur.

Our services were performed in accordance with the generally accepted standard of practice at the time this report was written. No warranty, expressed or implied, is intended.

LoSo appreciates being of service to ENVIRON International Corporation on this project. If you have any questions or require additional information, please contact us at (702) 596-2021.

Sincerely,

Logistical Solutions, LLC

Knistoper Everett

Kristopher Everett, CEM Project Manager NV Asbestos Consultant No. IM-1569

Attachment

Ty L. Salazar, CEM, OHST Operations Manager NV Asbestos Consultant No. IM-1413



	LEGEND	
Ν	Soil Stockpile	
	Approximate Scale:	1 inch ~ 48 feet

