

NDEP # 110630-02



Complaint/Spill Report Form

State of Nevada

Report Date: 6/30/2011 Report Time: 1557

Incident Date: 6/30/2011 Incident Time: 0610

Telephone: (888) 331-6337

Fax: (775) 687-8335

Do You Want to Remain Anonymous?

Reporting Person: Susan Crowley

Reporting Agency: Crowley Environmental

Address: 510 4th Street Phone: (702) 592-7727 Ext: _____

City: Henderson State: NV Zip: 89015 Zip+4: _____

Discharger/Owner/Operator of Facility: Nevada Environmental Response Trust

Address: 35 East Wacker Drive, Suite 1550 DOT#: _____

City: Chicago State: IL Zip: 60611 Zip+4: _____

Contact Person: Jay Steinberg Phone: _____ Ext: _____

Location of Complaint/Spill: Inside BMI Complex at the Veolia Water NA Perchlorate treatment site.
APN#: _____

City: Henderson State: NV County: Clark

Township: _____ Range: _____ Section: _____ Q,Q2: _____ Mile Marker: _____

Type of Material Discovered: Chromium

Concentration (% , ppm, ppb): 13 ppm

Quantity Found: 900 gals Media Affected: Soil

Cause of Complaint/Spill: _____ Container: Other

Broken conveyance line from extraction well which is part of chromium remediation system led to 900 gallon spill of groundwater containing chromium.

Remedial Action Taken:

Most of material was collected via vacuum truck (800 gals). 100 gals was lost to soil. Soil will be excavated and removed for appropriate disposal.

Oversight/Enforcement:

Email Address:

cc: NDEP BCA Remediation Statewide Jeff Collins

sharbour@ndep.nv.gov

cc: _____

jrcollins@ndep.nv.gov

cc: _____

glovato@ndep.nv.gov

smcrowley@cox.net

Comments:

Susan was wondering to whom R-Spill letter would be mailed.

Report Taken By: Jack Yates