



May 9, 2011

Mr. John Pekala  
ENVIRON International Corporation  
560 West Lake Mead Parkway  
Henderson, Nevada 89015

**Regarding:    *Final Visual Inspection – Pipe Abatement RZ-B21***  
**Nevada Environmental Response Trust**  
**560 West Lake Mead Parkway**  
**Henderson, Nevada 89015**  
**Project – CON111106**

Dear Mr. Pekala,

Logistical Solutions (LoSo) is pleased to provide ENVIRON International Corporation this *Letter Report for Final Visual Inspection of the Pipe Abatement in RZ-B21* conducted for the Nevada Environmental Response Trust site located at 560 West Lake Mead Parkway in Henderson, Nevada. The purpose of the final visual inspection was to identify, within reason, the presence and location of potential asbestos-containing materials (ACMs) within the regulated control zones of Remediation Zone-B21 (project area).

The scope-of-work performed as part of this final visual inspection included a visual survey of the project area and preparation of this letter report.

#### **Visual Site Inspection**

On May 5, 2011, Mr. Ty L. Salazar of LoSo was contacted by Steve Schafer of Earth Resource Group to conduct a final visual clearance inspection of the regulated asbestos zone located in RZ-B21 of the project area.

On May 6, 2011, LoSo performed a visual inspection of the regulated asbestos zones (see attached map) upon the completion of the asbestos abatement activities. The regulated asbestos zones were assessed for signs of visible ACM debris. No readily identifiable visual signs of asbestos debris were found within the regulated asbestos zones.

The visual inspection was conducted in a manner consistent with the recommendations specified in the American Society for Testing and Materials (ASTM) E1368-05e1 standard. This report applies only to the subject areas at the time of our inspection.

### **Limitations**

This report has been prepared for the exclusive use of ENVIRON International Corporation, as it applies to the subject regulated asbestos zone at the project area. Logistical Solutions, LLC is not responsible for any claims and damages associated with interpretation of available information. This assessment should not be regarded as a guarantee that future exposure to the airborne asbestos fibers will not occur.

Our services were performed in accordance with the generally accepted standard of practice at the time this report was written. No warranty, expressed or implied, is intended.

LoSo appreciates being of service to ENVIRON International Corporation on this project. If you have any questions or require additional information, please contact us at (702) 596-2021.


Sincerely,

**Logistical Solutions, LLC**



Ty L. Salazar, CEM, OHST  
Operations Manager  
Nevada Asbestos Consultant No. IM-1413

Attachments: Project Area Map



Aerial View - Tronox Asbestos Wrapped Pipe Abatement  
Map by Earth Resource Group  
AWP 1 - N 36° 2'29.22", W 115° 0'1.80"