



August 5, 2011

Mr. John Pekala
ENVIRON International Corporation
560 West Lake Mead Parkway
Henderson, Nevada 89015

**Regarding: *Visual Assessment of a Steel Pipe within RZ-C-45*
Nevada Environmental Response Trust
560 West Lake Mead Parkway
Henderson, Nevada 89015
Project No. CON111106**

Dear Mr. Pekala,

Logistical Solutions (LoSo) is pleased to provide ENVIRON International Corporation (ENVIRON) this report for a *Visual Assessment of a Steel Pipe within RZ-C-45* conducted for the Nevada Environmental Response Trust site located at 560 West Lake Mead Parkway in Henderson, Nevada. The purpose of the visual assessment was to identify, within reason, the presence and location of suspect asbestos-containing materials (ACMs) that may have been associated with a steel pipe located within RZ-C-45 (project area).

Las Vegas Paving Corporation (LVPC) uncovered a ten-foot portion of a two-inch-diameter steel pipe during excavation and grading activities. As a result of this discovery, ENVIRON contacted LoSo to assess for suspect ACMs that might be associated with the pipe.

Visual Site Inspection

On August 3, 2011, LoSo was contacted by Mr. John Pekala of ENVIRON to conduct a visual assessment of the exposed pipe. The steel pipe was oxidized (rusted) and partially decomposed into the surrounding soil. Thermal system insulation (TSI) and pipe wrap was not observed in the exposed section of the pipe. Based on this information, suspect ACMs were not observed in association with the aforementioned pipe located within RZ-C-45.

The visual assessment was conducted in general accordance with the protocols established in EPA Regulation 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA). This report applies only to the oxidized steel pipe that was observed at the time of our visual assessment.

Limitations


This report has been prepared for the exclusive use of ENVIRON International Corporation, as it applies to the project area. Logistical Solutions, LLC is not responsible for any claims and damages associated with interpretation of available information. This assessment should not be regarded as a guarantee that future exposure to the airborne asbestos fibers will not occur.

Our services were performed in accordance with the generally accepted standard of practice at the time this report was written. No warranty, expressed or implied, is intended.

LoSo appreciates being of service to ENVIRON International Corporation on this project. If you have any questions or require additional information, please contact us at (702) 596-2021.

Sincerely,

Logistical Solutions, LLC



Kristopher Everett, CEM
Project Manager
NV Asbestos Consultant No. IM-1569



Ty L. Salazar, CEM, OHST
Operations Manager
NV Asbestos Consultant No. IM-1413