


LOUs within Remediation Zone A:
 LOU 59 - Storm sewer system
 LOU 62 - State Industries, Inc. site including impoundments and catch basin



- Legend**
- ⊕ Phase A Sample Location (2006)
 - Phase B Sample Location (2008-2009)
 - Analytes Detected Above BCL
 - Analyte Not Detected Above BCL (less than 10 ft bgs)
 - LOU Boundaries
 - Associate LOU Pipelines
 - LOU #59 Storm Sewer System
 - Site features (Buildings and Tanks)
 - Remediation Zone Boundary

REMEDIATION ZONE A SOIL SAMPLE LOCATIONS Tronox LLC Henderson, Nevada		
SCALE: 1 in = 150 ft	DATE: 06/17/10	PROJECT NUMBER: 2027.07

DESIGNED BY: NGEM	REVISIONS			
DRAWN BY: NGEM	NO.	DESCRIPTION	DATE	BY
CHECKED BY: NGEM				
APPROVED BY: NGEM				

northgate
environmental management, inc.

TRONOX <http://www.ngem.com>

FIGURE NUMBER:
3

SHEET NUMBER:
1