



- Asbestos Sample Location
- Remediated Areas\*

February 2007 Aerial from AirPhotoUSA.

BEC / Tronox Parcels A/B Data Review  
 BMI Common Areas, Henderson, Nevada

FIGURE 1

**AMPHIBOLE ASBESTOS  
 REMEDIATION AREAS**



\*These areas have had a minimum of 4" of soil removed for remediation purposes.

Prepared by: MKJ Date: 12/17/07

JOB No. 0069073  
 FILE: GIS/BEC/TRONOX/FIGURE\_4.MXD