



- Asbestos Sample Location
- Remediated Areas*

February 2007 Aerial from AirPhotoUSA.

BEC / Tronox Parcels A/B Data Review
 BMI Common Areas, Henderson, Nevada

FIGURE 1

**AMPHIBOLE ASBESTOS
 REMEDIATION AREAS**



*These areas have had a minimum of 4" of soil removed for remediation purposes.

Prepared by: MKJ Date: 12/17/07

JOB No. 0069073
 FILE: GIS/BEC/TRONOX/FIGURE_4.MXD