



July 1, 2011

Mr. John Pekala
ENVIRON International Corporation
560 West Lake Mead Parkway
Henderson, Nevada 89015

Regarding: ***Final Visual Inspection***
 Pipe Abatement RZ-D-11, RZ-D-11A, and RZ-D-11B
 Nevada Environmental Response Trust
 560 West Lake Mead Parkway
 Henderson, Nevada 89015
 Project No. - CON111106

Dear Mr. Pekala,

Logistical Solutions (LoSo) is pleased to provide ENVIRON International Corporation this *Letter Report for Final Visual Inspection of the Pipe Abatement in RZ-D-11, RZ-D-11A, and RZ-D-11B* conducted for the Nevada Environmental Response Trust site located at 560 West Lake Mead Parkway in Henderson, Nevada. The purpose of the final visual inspection was to identify, within reason, the presence and location of potential asbestos-containing materials (ACMs) within the regulated control zones within Remediation Zones RZ-D-11, RZ-D-11A, and RZ-D-11B (project area).

Earth Resource group excavated soil from the top portion of the asbestos-wrapped pipe on the evening of June 22, 2011 into June 23, 2011. The entire length of pipe contained an asbestos-containing pipe wrap that was black in color. The piping was abated due to the presence of asbestos by Earth Resource Group on the evening of June 22, 2011 into June 23, 2011. The attached site plan depicts the general location of the piping that was removed.

Visual Site Inspection

On June 23, 2011, Mr. Kristopher Everett of LoSo was contacted by Steve Schafer of Earth Resource Group to conduct a final visual clearance inspection of the regulated asbestos zone located within RZ-D-11, RZ-D-11A, and RZ-D-11B. Mr. Everett performed a visual inspection on the same day he was contacted by Mr. Schafer. The regulated asbestos zone was assessed for signs of visible ACM debris. Asbestos and/or asbestos containing debris was not observed during the inspection of the regulated asbestos zone.

The visual inspection was conducted in a manner consistent with the recommendations specified in the American Society for Testing and Materials (ASTM) E1368-05^{e1} standard. This report applies only to the subject areas at the time of our inspection.

Limitations


This report has been prepared for the exclusive use of ENVIRON International Corporation, as it applies to the subject regulated asbestos zone at the project area. Logistical Solutions, LLC is not responsible for any claims and damages associated with interpretation of available information. This assessment should not be regarded as a guarantee that future exposure to the airborne asbestos fibers will not occur.

Our services were performed in accordance with the generally accepted standard of practice at the time this report was written. No warranty, expressed or implied, is intended.

LoSo appreciates being of service to ENVIRON International Corporation on this project. If you have any questions or require additional information, please contact us at (702) 596-2021.

Sincerely,

Logistical Solutions, LLC




Kristopher Everett, CEM
Project Manager
NV Asbestos Consultant No. IM-1569




Ty L. Salazar, CEM, OHST
Operations Manager
NV Asbestos Consultant No. IM-1413


Attachment



LEGEND

N Asbestos-Wrapped Pipe 

Approximate Scale: 1 inch ~ 65 feet



SITE PLAN

Nevada Environmental Response Trust
Remediation Zone RZ-D-11, 11A, & 11B

Project Number
CON111106

